

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29493
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	KERSHAW, L. R.
8. Well No.	12
9. Pool Name or Wildcat	WEIR BLINEBRY, EAST
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3557' GL

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter C : 660 Feet From The NORTH Line and 1650 Feet From The WEST Line Section 13 Township 20-S Range 37-E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3557' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER: ☐	CASING TEST AND CEMENT JOB ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-06-97: MIRU. PMP STUCK BACK OFF RDS. INSTL TRIPLE BOP & SWAB DOWN TBG DN FLOWLINE.
11-07-97: TIH W/BIT & CSG SCRAPER. TAG UP @ 6885'.
11-10-97: TIH W/CIBP & SET @ 6577'. TIH W/BAILER & DUMP 15' CMT ON TOP OF CIBP. TIH W/TBG TO 6500' & CIRC HLE W/2% KCL FW. TST CIBP TO 1000#-OK. PERF 5766-5770, 5795-5804, 5838-5850, 5852-5862, 5868-5872, 5875-5882, 5890-5893, 5895-5902, 5914-5918, 5936-5940, 5942-5946, 5948-5950, 6016-6022.
11-11-97: TIH W/PKR ON TBG. TEST IN @ 5000#. PSA 5726'. LOAD & TEST BACKSIDE TO 500#-OK. ACIDIZE 5766-6022' W/6000 GALS 15% NEFE HCL W/180 BALLS & 1500# RK SLT. PMPD IN 3 STGS. SWAB. RECVD 0 BO, 35 BLW.
11-12-97: SWAB. FL @ 4500'. ENDING FL @ 5500'.
11-13-97: REL PKR & LOWER TO 6100 & KNOCK OFF BALLS.
11-14-97: TIH W/PKR ON TBG. TEST TO 8000#. PSA 5665'. LOAD & TEST CSG TO 1000#-OK. INSTL TIW VALVE IN TBG.
11-17-97: FRAC 5766-6022 W/15,000 GALS 35# BORATE X-LNKD GEL PAD W/124,500# 20/40 BRADY SD. TAIL IN W/7000 GALS GEL. REL PKR. RAN BIT ON TBG. TAG SD FILL @ 6423'.
11-19-97: RAN 2" OPEN ENDED SN, TBG, TBG ANCHOR. REM BOP. LAND SN @ 6215'. TA @ 5693'. SPACE PUMP @ 7". LOAD TBG W/10 BFW. TEST TBG TO 500#-OK. RD. ON PRODUCTION @ 5:30 PM.
11-20 THRU 12-07-97: PUMPING & TESTING
12-08-97: ON 24 HR OPT. PUMPED 15 BO, 9 BW, & 59 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	<i>J. Denise Leake</i>	TITLE	Engineering Assistant	DATE	2/18/98
TYPE OR PRINT NAME	J. Denise Leake	Telephone No.	397-0405		

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR TITLE DATE MAR 06 1998

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: