## Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240  OIL CONSERVATION P.O. Box 1980, Hobbs, NM 88240	N DIVISION WELL API NO.
DISTRICT II Santa Fe. New Mexico 87	750-2088
P.O. Drawer DD, Artesia, NM 88210  DISTRICT III	5. Indicate Type of Lease  STATE THE FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF DIFFERENT RESERVOIR. USE "APPLICATION FOR PERM (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL GAS WELL XX WELL OTHER	Eunice Monument South Unit
2. Name of Operator Chevron U.S.A. Inc.	8. Well No.
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Pool name or Wildcat Eunice Monument (GB/SA)
4. Weil Location	
Unit Letter C : 660 Feet From The North	Line and1980 Feet From The West Line
Section 30 Township 20S Range	
10. Elevation (Show whether DF	3536
11. Check Appropriate Box to Indicate Na	:
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON I	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB
OTHER: add perfs, acidize, return to prod. x	отнея:
12. Describe Proposed or Completed Operations (Clearly state all perment details, and work) SEE RULE 1103.  It is proposed to add nine sets of perfs in (3616-22, 3633-3638, 3685-92, 3700-04, 3730 3870-74, 3878-82. 46 holes total) Acidize residue, and return to production.	n the Grayburg zones 1 thru 5 0-34, 3768-72, 3812-16, 3820-24,
I hereby certify that the information above is true and complete to the best of my knowledge and be SKINATURE & SIMONE TITLE  TYPE OR PRINT NAME	sid. — Clechnical Assistant DATE 1-9-89 — TELEPHONE NO.
(This space for State Use)	
MCTXES VAREL VE DEMORAL LANGUAGO	
APPROVED BY DISTRICT I SUPERVISOR TITLE	DATE