Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised 1-1-89

| PER NOT LIKE | WELL API NO. | |
|--|---|--|
| P.O. Box 2088 DISTRICT II Santa Fe, New Mexico 87504-2088 | 30-025-30265 | |
| DISTRICT III | 5. Indicate Type of Lease STATE XX FEE | |
| 1000 Rio Brazos Rd., Aztec, NM 87410 | 6. State Oil & Gas Lease No. | |
| SUNDRY NOTICES AND DEPORTS ON WELLS | LG-6555 | |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | 7. Lease Name or Unit Agreement Name | |
| 1. Type of Well: OIL GAS WELL X OTHER | Chiso -B-, 8711 JV-P Com | |
| 2. Name of Operator | 8. Well No. | |
| BTA 011 Producers 3. Address of Operator | 9. Pool name or Wildcat | |
| 104 S. Pecos, Midland, TX 79701 | Ojo Chiso, Morrow | |
| Unit Letter K : 1980 Feet From The South Line and 231 | NMPM Lea County | |
| | SSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK | XX ALTERING CASING | |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING | G OPNS. PLUG AND ABANDONMENT | |
| PULL OR ALTER CASING CASING TEST AND C | EMENT JOB | |
| OTHER: OTHER: OTHER: | f water zone | |
| Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incluwork) SEE RULE 1103. | | |
| 11-11-91: TD 13,310', PB 12,750', RU Wireline, RIH w/2 test plug to 500 psi, Perf 1-1/2" hole @ 10, | | |
| | 598'. | |
| test plug to 500 psi, Perf 1-1/2" hole @ 10, | 598'. tbg, Swbg & tstg. | |
| test plug to 500 psi, Perf 1-1/2" hole @ 10, 11-12-91: RIH w/5" CIBP to 12,740' & set, RIH w/4000' | 598'. tbg, Swbg & tstg. | |
| test plug to 500 psi, Perf 1-1/2" hole @ 10, 11-12-91: RIH w/5" CIBP to 12,740' & set, RIH w/4000' 11-14-91: A w/1500 gals 50-50 7-1/2% MSA & methanol, S 11-20-91: PB 12,740, Put well down sales line. | 598'. tbg, Swbg & tstg. | |
| test plug to 500 psi, Perf 1-1/2" hole @ 10, 11-12-91: RIH w/5" CIBP to 12,740' & set, RIH w/4000' 11-14-91: A w/1500 gals 50-50 7-1/2% MSA & methanol, S 11-20-91: PB 12,740, Put well down sales line. Thereby certify that the information above is true and complete to the best of my knowledge and belief. Signature Advisory Advisor | tbg, Swbg & tstg. wbg & tstg. minstrator DATE 12-9-91 | |
| test plug to 500 psi, Perf 1-1/2" hole @ 10, 11-12-91: RIH w/5" CIBP to 12,740' & set, RIH w/4000' 11-14-91: A w/1500 gals 50-50 7-1/2% MSA & methanol, S 11-20-91: PB 12,740, Put well down sales line. Thereby certify that the information above is true and complete to the best of my knowledge and belief. Signature Additional Time Regulatory Additional Complete to the best of my knowledge and belief. | tbg, Swbg & tstg. wbg & tstg. | |