

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-30520
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 010709

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name: DK
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well No. 3
2. Name of Operator Falcon Creek Resources		9. Pool name or Wildcat DK Drinkard , Blinebry
3. Address of Operator 621 17 th Street, Suite 1800, Denver CO 80293		
4. Well Location Unit Letter <u>B</u> : <u>660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>25</u> Township <u>20S</u> Range <u>38E</u> NMPM County <u>Lea</u>		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3566 GL		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: Drill out CIBP, Add Drinkard and Blinebry perfs, Isolate and test separately. ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
As of 3-15-00 operator has not performed this work
Plans are to initiate workover in next 60 days ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

OPERATOR PROPOSES:

- 1.) Drill out CIBP at 6850'
- 2.) Perforate Drinkard; 6902-6910, 6917-6927, 6940-6948, 6952-6957, 6974-6978, 7015-7019, 7031-7038.
- 3.) Isolate, stimulate and test.
- 4.) Perf Blinebry, 6535-6545, 6410-6416, 6244-6452, 6270-6288, 6158-6173, 6116-6123, 6130-6134, 6030-6050.
- 5.) Stimulate and test.
- 6.) Operators intention is to then commingle Abo, Drinkard, Tubb and Blinebry

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gerald Lucero TITLE Manage Operations DATE 3-15-00

Type or print name Gerald Lucero Telephone No. 303-675-0007

(This space for State use)

APPROVED BY _____ TITLE _____ DATE April 1, 2000
Conditions of approval, if any: