

N.M. OIL CONS. COMMISSION
P.O. BOX 1980

Form 3160-5
(June 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
CONOCO INC.

3. Address and Telephone No.
10 Desta Drive STE 100W, Midland, TX 79705 (915) 686-6551

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL, 660' FEL
SEC. 28, T-20S, R-38E.

5. Lease Designation and Serial No.

LC 031695B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

WARREN UNIT # 95

9. API Well No.

30-025-30659

10. Field and Pool, or Exploratory Area

BLINEBRY/TUBB/DRINKARD

11. County or Parish, State

LEA, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
☐ Notice of Intent	☐ Abandonment
☒ Subsequent Report	☐ Recompletion
☐ Final Abandonment Notice	☐ Plugging Back
	☐ Casing Repair
	☐ Altering Casing
	☒ Other ADD PAY / STIMULATE
	☐ Change of Plans
	☐ New Construction
	☐ Non-Routine Fracturing
	☐ Water Shut-Off
	☐ Conversion to Injection
	☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9-12-94 MIRU. POOH W/BLINEBRY & DRINKARD TBG & PKR. RIH W/DEDA-1JT BUTTRESS 1.5 PROFILE-7JTS BUTTRESS-PKR W/1.73 PROFILE. SET PKR @ 6550'. GET OFF ON/OFF TOOL. POOH. RIH W/7" RBP & PKR. SET RBP ABOVE BOMBS. BAD TEST. POOH PKR. RBPP. RIH W/TENSION PKR SET @ 6550' POOH W/BOMBS, TBG, & PKR. RIH W/SCRAPPER TO 6878'. POOH. RIH W/RBP & PKR. SET RBP @ 6550' & PKR @ 6545'. POOH. PERF 15PF-BLINEBRY 1-3.5756-59.71-75.81-83.98-5806.16-22.68-74.79-86.5938-50.61-65.70-79. BLINEBRY 5-6212-16.25-34.58-65.84-88.91-94. TUBB-6381-85.90-94.6401-09.19-29.36-46.61-66.70-77.6501-06.17-27. RIH W/PKR @ 6350 & RBP @ 6540. ACID TUBB W/3600 GAL 15%. NEFE HCL & 108 BALL SEALERS. MOVED RBP @ 6335 & PKR @ 6190. ACID BLINEBRY 5 W/1600 GAL 15% NEFE HCL & 48 BS. ACID BLINEBRY 1-3 W/3550 GAL 15% NEFE HCL & 107 BS @ 2-3 BPM. POOH W/RBP & PKR. RIH W/ 4 1/2 TBG & PKR @ 6330. PUMPED 10,000 GAL SPECTRA G-3500 DUMMY FRAC TAGGED W/RAM. FRACTURED TUBB W/53,000 GAL SPECTAR G-4000 W/102,000# 16/30 OTTAWA SAND #8 38,000# RCS TAGGED W/RAM. POOH W/4 1/2. RIH W/RBP ON 2" @ 6317. POOH. RIH W/PKR ON 4 1/2 @ 2823. PUMPED 30,000 GAL SPECTRA-G-4000 DUMMY FRAC TAGGED W/RAM. FRAC BLINEBRY ZONES 1-5 W/145,000 GAL SAME & 285,000# 16/50 OTTAWA SAND & 207,000# 16/30 LCS TAGGED W/RAM. POOH. RIH W/SHOE, 6JTS WASH PIPE, JARS & DC. POOH. RIH W/RETRIEVING HEAD. TAG RBP & POOH. LOG INDICATED ALL ZONES TREATED. RIH W/PKR. LONG STRING. SHORT STRING. LAST DATED 11-8-94. OIL 44, WTR 8, GAS 1489, TP 200, OPEN CHOKE.

14. I hereby certify that the foregoing is true and correct

Signed

[Signature]

Title

STAFF REGULATORY ASSISTANT

Date

11-12-94

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

ACCEPTED FOR RECORD

Date

4 1994

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See instruction on Reverse Side

CARLSBAD, NEW MEXICO

RECEIVED

DEC 18 1934

OOD BOARD
OFFICE