

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.HUBBS OFFICE D.C.C.
101-058678

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR Shell Oil Company (Western Division)		7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR P.O. Box 1509, Midland, Texas 79701		8. FARM OR LEASE NAME Federal
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 2310' FWL & 2310' FWL (SE/4 NW/4) Section 4, T-22-S, R-34-E, BPM Survey, Lea County, New Mexico		9. WELL NO. 1
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Gran Ridge-Morrow Gas
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3643' DF		11. SEC., T., R., S. OR B.E. AND SURVEY Sec. 4, T-22-S, R-34-E BPM
		12. COUNTY OR PARISH 13. STATE Lea New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIR WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completions on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Treat w/1300 bbls pregelled Synthetic Brine using 40% of W-3 and 25% of Aquafac.
2. Load tubing with gelled brine. Frac perforations 12,882' - 13,111'.
3. Shut well in and run temperature log.
4. Place on production.

18. I hereby certify that the foregoing is true and correct

Original Signed By **J. D. Duren**
SIGNED **J. D. DUREN**TITLE **Staff Petrophysical Engineer** DATE **June 3, 1967**

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands owned by any State, on all lands owned by any State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between, and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well sealed conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1965-O-682228

9-57-5-11

Original Signed By
J. D. DUREN