

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-31559	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT	
8. Well No. 178	
9. Pool name or Wildcat ARROWHEAD/GB	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL _____ GAS _____ WELL <input checked="" type="checkbox"/> WELL <input type="checkbox"/> OTHER _____	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	
4. Well Location Unit Letter _____ N _____ : _____ 510 Feet From The _____ SOUTH Line and _____ 1980 Feet From The _____ WEST Line Section _____ 1 _____ Township _____ 22S Range _____ 36E NMPM LEA County _____	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3498 GE	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: _____ <input type="checkbox"/>
SUBSEQUENT REPORT OF:	
REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input type="checkbox"/>
CASING TEST AND CMT JOB <input type="checkbox"/>	OTHER: DRILLING SUMMARY <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU, RID-RIC #4 ON 4-27-92.
SPUD 12 1/4" HOLE AND DRILL TO 1201'.
RUN 8 5/8" CASING TO 1201' AND PUMP 900 SXs. OF CEMENT, CIRC. 10 SXs. TO SURFACE.
WAIT ON CEMENT FOR 12 HOURS. TEST CASING TO 1000 PSI-OK.
DRILL OUT FLOAT AND SHOE, CONTINUE ON TO 3915' TD HOLE.
LOG HOLE, RUN 5 1/2" CASING TO 3915'. PUMP 700 SXs. OF CEMENT AND CIRCULATE 21 SXs. TO SURFACE.
NIPPLE UP WELLHEAD AND TEST TO 3000 PSI-OK.
RELEASE RIG ON 5-3-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	<u>P.R. Matthews</u>	TITLE	TECH. ASSISTANT
DATE:		5/4/92	
TYPE OR PRINT NAME	P.R. MATTHEWS		TELEPHONE NO (915)687-7812
APPROVED BY	<u>Paul Kautz</u> Geologist	TITLE	
CONDITIONS OF APPROVAL, IF ANY:		DATE	MAY 06 '92