Submit 3 Copies to Appropriate

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office	OIL	CONSERV	/ATION	DIVISIO	NC					
		P.O. 8	3ox 2088							
DISTRICT !		Santa Fe, N	ew Mexico	o 87504-2	2088					
P.O. Box 1980, Hobbs, NM 882	40									
DISTRICT II						API NO. (assi	gned by OCD on Ne	w Weils)		
P.O. Drawer Dd, Artesia, NM 88	210					30-025-	31631 🗸			
DISTRICT III 1000 Rio Brazoe Rd., Aztec, Nm 87410						6. Indicate Type of Lease STATE FEE X				
						6. State Oil	& Gas Lease No.			
						N/A				
	SUNDRY NOTIC	ES AND REPO	ORTS ON V	VELLS						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"						7. Lease Name or Unit Agreement Name				
	(FORM C-101) F	OR SUCH PROPO	SALS.)			ARROWHEAD GRAYBURG UNIT				
1. Type of Well:	CAC				<del></del>	1			•	
WELL X	GAS WELL \ \ O	THER								
2. Name of Operator		THEN								
CHEVRON U.S.A. INC.						8. Well No. 197				
Address of Operator     P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE						9. Pool name or Wildcat ARROWHEAD/GB				
4. Well Location						7 11 11 10 111	ICAD/GD			
Unit Letter	<u>H 2</u> :2	210 Feet From TI		NORTH	Line and		Feet From The	EAST	Line	
Section 12		Township	22S		Range	36E	NMPM	LEA	County	
		TO. EIEVIN	3456 GE		, GH, etc.)					
11	Check Appropriate	Box to Indecate			. or Othe	r Data				
NOTICE OF	INTENTION TO:		1			EPORT O	F:			
PERFORM REMEDIAL WORK	PLUG AND ABANDO	N N	REMEDIAL WO	DRK			ALTER CASING	i	П	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE	DRILLING OPN	s. 🗖		PLUG AND ABA	w.		
PULL OR ALTER CASING	7	_	CASING TEST	AND CMT JO	.в. 🗀					
OTHER:	<del></del>		OTHER:		SC	ı DZ PERFS,	ADD NEW F	PERFS		
			-			AME ZON				
12. Describe Proposed or Comp esticated date of starting any	leted Operations(Clearly s proposed work) SEE RUL	tate all pertinent det E 1103.	als, and give pe	ertinent dates, i	including					
	ORMED 12-9 TH									
ND WH, NU	BOPE, SET RBP	@ 3685, CAI	P WITH 20	SAND.	RIH W/F	PKR				
	Z PENROSE PER						NT TO 3672			
CIRC CLEAN	I, SWAB SQUEEZ	ED PERFS FO	OR FLUID E	NTRY, CI	EAN Ω	UT TO RE	BP RETRIEVE	RRP		
	3704' WITH 2 II						, IIC IIIC V L			

PERF 3690-3704' WITH 2 JHPF W/4" CASING GUN. TOTAL 22 HOLES. ACDZ EACH SET OF NEW PERFS WITH 2 BBLS 15% NEFE HCL. SWAB BACK LOAD. RUN TUBING, ND BOP, PLACE ON PRODUCTION

I hereby certify that the information shove is true and complete to the best of my knowledge and belief.										
SIGNITURE	Mita Rice	TITLE	TECHNICAL ASSISTANT	DATE:	1/13/93					
TYPE OR PRINT NAME	PRINT NAME NITA RICE			TELEPHONE NO. (915)687-7436						
APPROVED BY CONDITIONS OF APPROV	Orig. Signed by Paul Kautz	TITLE		DATE	24 24 3					