

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer 0d, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-31631	
6. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
8. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name ARROWHEAD GRAYBURG UNIT	
8. Well No. 197	
9. Pool name or Wildcat ARROWHEAD/GB	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator CHEVRON U.S.A. INC.	
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	
4. Well Location Unit Letter H : 2210 Feet From The NORTH Line and 990 Feet From The EAST Line Section 12 Township 22S Range 36E NMPM LEA County 10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3456 GE	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTER CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABAN. <input type="checkbox"/> CASING TEST AND CMT JOB <input type="checkbox"/> OTHER: DRILLING SUMMARY <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU ROD-RIC #4 ON 7-23-92, SPUD 12 1/4" HOLE AT 3:30 P.M.
DRILL AND SURVEY FROM 0'-1175', TD 12 1/4" HOLE.
RUN 8 5/8" CASING TO 1175', PUMP 883 SX. CMT AND CIRC. 20 SXs. TO SURFACE.
WOC FOR 23.5 HOURS.
DRILL OUT CMT. AND FLOAT, TEST CASING TO 1000#-OK.
DRILL AND SURVEY FROM 1175'-3875', TD HOLE.
RUN 5 1/2" CASING TO 3875', PUMP 900 SXs. CEMENT AND CIRC. 75 SXs. TO SURFACE.
INSTALL WELLHEAD AND TEST-OK.
RELEASE RIG ON 7-30-92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <u>P.R. Matthews</u>	TITLE <u>TECH. ASSISTANT</u>	DATE: <u>8-3-92</u>
TYPE OR PRINT NAME <u>P.R. MATTHEWS</u>		TELEPHONE NO. <u>(915)687-7812</u>

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY <u>DISTRICT I SUPERVISOR</u>	TITLE <u></u>	DATE <u>AUG 06 '92</u>
CONDITIONS OF APPROVAL, IF ANY: <u></u>		

RECEIVED

AUG 05 1992

OCD HOBBS OFFICE