Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department Form C-103 Revisied 1-1-89

District Office		OIL C	ONSERV	ATION	DIVIS	ION			
				ox 2088					
DISTRICT I		Sa	nta Fe, Ne	ew Mexic	co 87504	-2088			
P.O. Box 1980, Hobbs, NM 88240							ADIAIO (seeigned by OCD on New Welle)		
DISTRICT II							API NO. (assigned by OCD on New Wells)		
P.O. Drawer Dd, Artesia, NM 88210 DISTRICT III							5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, Nm 87410							J. Indicate 1, 7	STATE X	FEE
							0.000000000	See Leese No.	
							6. State Oil &	Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS							N/A		
								or Unit Agreement N	ame
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"							ARROWHEAD GRAYBURG UNIT		
(FORM C-101) FOR SUCH PROPOSALS.)									
1. Type of Well:							1		
OIL		AS	15.150	TOD					
WELL OTHER INJECTOR									
2. Name of Operator							8, Well No.		
CHEVRON U.S.A. INC.							171		
3. Address of Operator P.O. P.O.Y. 1150, MIDLAND, TY 79702, ATTN: P.R. MATTHEW/S							ARROWHEAD/GB		
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS							Allinoviieneros		
Unit Letter	K	: 221	5 Feet From Th	ne	WEST	Line and	2305		SOUTH Line
Section	2		Township	22S		Range	36E	NMPM LEA	County
			10. Elevatio	on(Show whe	ther DF, RKB,)		
			<u>///</u>		3523 GI				
11 NC		Check Appropriate Bo	x to Indecate	Nature of			ner Data REPORT OF :		
	TICE OF INT	PLUG AND ABANDON	\Box	REMEDIAL				ALTER CASING	
PERFORM REMEDI	=		-			,,, 	4	PLUG AND ABAN.	
TEMPORARILY AB	· -	CHANGE PLANS			E DRILLING O	 		PLUG AND ABAN.	Щ
PULL OR ALTER C	ASING			1	ST AND CMT				
OTHER:				OTHER:	DRILLIN	G SUMIN	JARY		
				<u> </u>					
		Operations(Clearly state osed work) SEE RULE 1		tails, and give	e pertinent dati	es, including	l		
351154113213		,							
MIRU ROD-RIC #4 IN 9-23-92. SPUD 12 1/4" HOLE AND DRILL TO 1432', TD 12 1/4" HOLE.									
RUN 8 5/8" CASING TO 1432'. PUMP 900 SXS. CEMENT AND CIRC. 194 SXS. TO SURFACE.									
WAIT ON CEMENT FOR 12.5 HRS. DRILL OUT FLOAT AND SHOE.									
DRILL TO TD AT 3995' WITH A 7 7/8" BIT.									
RUN 5 1/2" CASING FROM SURFACE TO 3995'.									
PUMP 825 SXS. CEMENT.									
INSTALL WELLHEAD AND RELEASE RIG ON 9-30-92.									
		_							
I hereby certify the	the impression at	pove is true and complet	e to the best of						
SIGNITURE #	. K. ///a	elle	TITLE	TECH.	ASSISTA	NT	DATE:	<u> 10-1-92</u>	
TYPE OF PRINT N	AAAE	P.R. MATTHEWS	3				TELEPHONE NO	o. (915)687-78	312
TYPE OR PRINT N	1 10, 13	igned by		. ' =					
	Peul	Kautz						act 0	5 '9 2
APPROVED BY		logist	TITLE				DATE		
CONDITIONS OF	APPROVAL, IF ANY	:							