

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31889
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-134

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Kiwi AKX State
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 8
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat East Livingston Ridge Delaware

4. Well Location Unit Letter F : 1980 Feet From The North Line and 2310 Feet From The West Line Section 16 Township 22S Range 32E NMPM Lea County
---

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3746' GR
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate, Treat <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-30-93. Perforated 7183-7185' w/6 - .42" holes (2 SPF). TIH w/packer and RBP. Set RBP at 7220'. Tested to 1500 psi. Circulated hole with 2% KCL. Straddled perms 7183-85' and acidized w/500 gals 7½% HCL. Swabbed dry.

4-1-93. Frac'd perms 7183-85' w/500 gals 35# linear gel, 4350 gals 35# XL gel with 12000# 16/30 resin-coated sand. Washed sand off RBP. TIH with pump and rods and hang well on pump. Well producing from perforations 7183-7185'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 4-7-93

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY JERRY SEXTON TITLE REGIONAL SUPERVISOR DATE APR 12 1993

CONDITIONS OF APPROVAL, IF ANY: