

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

W	API NO. 30-025-31986
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. V-2667	
7. Lease Name or Unit Agreement Name Ottawa State	
8. Well No. 1	
9. Pool name or Wildcat Wildcat Delaware	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Dry	
2. Name of Operator Siete Oil and Gas Corporation	
3. Address of Operator P.O. Box 2523, Roswell, NM 88202-2523	
4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>22S</u> Range <u>32E</u> NMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3797' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/11/93 Set 1st plug @ 8705'-8600' w/40 sxs "C" Neet, set 2nd plug @ 7000'-6900' w/40 sxs "C" Neet, set 3rd plug @ 4250' w/40 sxs "C", 4% CaCl, tagged plug, no fill, set 4th plug @ 4250' w/40 sxs "C", 4% CaCl, tagged plug, no fill, set 5th plug @ 4250' w/75 sxs "C", 4% CaCl, tagged plug, TOC @ 4095', set 6th plug @ 750'-650' w/30 sxs "C" Neet, set 7th plug @ 35'-surface w/10 sxs "C" Neet, cutoff well head, install dry hole marker, released rig @ 11:00 pm.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cathy Batley-Bailey TITLE Reg. Spec. DATE 8/17/93
TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

FOR RECORD ONLY

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: Well re-enter 9/20/93
by WTI RCB Ltd

RECEIVED

SEP 28 1993

**OCD HOBBS
OFFICE**