Form C-102 Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088 Santa Fe, New Mexico 87504-2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

WELL LOCATION AND ACREAGE DEDICATION PLAT

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

All Distances must be from the outer boundaries of the section

Operator	CAPAT	AZ OF	PERATIN	1G, IN	IC		Lee	ase		RHIN	10			Well No.	1	
Unit Letter	Section	1	To	wnship			Rai	nge			·····		County			
N		11		2	0 SO	UTH			38	EAST	NMP!	М		LEA		
Actual Footage L	ocation o	f Well:														
	eet from t		SOUTH		ne and		Po	1980	1201		feet fro	om t	he WES	line Dedicated	Acres	
Ground Level El	- 10		Forma - Se		Divo	^C		South,	House	Y-SR	Gas				60	
3584.3																Acres
 Outline the If more that 													as to workin	s interest	and rova	ltv).
3. If more that unitization,	an one lea	ase of c	different etc.?	owner	ship is	dedica	ited to th	e well, ha	ave the							
Yes		ИМ				-	type of co									
If answer is " this form nece		fowne	rs and t	tract d	escript	io ns w	hich have	actually	been co	nsolida	ted. (Use r	eve	rse side oi			
No allowable	will be	assigne	d to th	ne well	unit	all in	terests h	ave been	consol	idated	(by comm	uni	tization, u	nitization,	forced-	pooling.
otherwise) or	until a	non-st	andard	unit, e	limina	ting s	uch inter	est, has	been ap	proved	by the Div	risio T		1 1		
F						T			T				OPERA'	OR CER	TIFICA	TION
									1				contained		ind comp	
		i I				1			i				best of free k	and age and	belief.	
		İ							i		7	Ħ	Signature	X		
									i			ΙL	H. Scot			
		1							i				Printed Na	me		
		_				<u> </u>			<u> </u>				Agent			
		_ T		'					1			i l	Position	. 0		T
		l i				1			1			 -	Capataz Company	uperat	ing.	inc.
		1				1								19-93		
													Date			
									1				SURVE	OR CER	TIFICA	TION
						 			+			1	I hereby ceri	ify that the	well loca	tion shown
									1				on this plat	_		
		1							1			$ \ $	supervison,			
									1				correct to belief.			
													Date Surv	yed IUNE 15,	1993	
	- 1980	 - 	···· >	- 					 				Signature Profession	& Sad	JONES	les
		<u> </u>	···	Ĭ I]	Certification	POFE DS FORME	Section 1	ST. 676 SON, 3239 NES, 7977
0 330 6	60 990	1320	1650	1980 2	2310 2	640	2000	1500) 100	00	500	0		93-11-		