# CONTINGENCY PLAN SHOULD H2S BE ENCOUNTERED WHILE DRILLING

#### 13-A

- 1. All Company and Contract personnel admitted on location must be trained by a qualified H<sub>2</sub>S safety instructor to the following:
  - A. Characteristics of H2S
  - B. Physical effects and hazzards
  - C. Proper use of safety equipment and life support systems.
  - D. Principle and operation of H<sub>2</sub>S detectors, warning system and briefing areas.
  - E. Evacuation procedure, routes and first aid.
  - F. Proper use of 30 minute pressure demand air pack.

# 2. H<sub>2</sub>S Detection and Alarm Systems

A. H<sub>2</sub>S detectors and audio alarm system to be located at bell nipple, end of blooie line (mud pit) and on derrick floor or doghouse.

## 3. Windsock and/or wind streamers

- A. Windsock at mudpit area should be high enough to be visible.
- B. Windsock at briefing area should be high enough to be visible.
- C. There should be a windsock at entrance to location.

### 4. Condition Flags and Signs

- A. Warning sign on access road to location.
- B. Flags to be displayed on sign at entrance to location. Green flag, normal safe condition. Yellow flag indicates potential pressure and danger. Red flag, danger, H<sub>2</sub>S present in dangerous concentration. Only emergency personnel admitted to location.

# 5. Well control equipment

A. See exhibit "E"

#### 6. Communication

- A. While working under masks chalkboards will be used for communication.
- B. Hand signals will be used where chalk board is inappropriate.
- C. Two way radio will be used to communicate off location in case of emergency help is required. In most cases cellular telephoned will be available at most drilling foreman's trailer or living quarters.

### 7. Drillstem Testing

- A. All testing will be done in daylight hours.
- B. Exhausts will be watered
- C. Flare line will be equipped with an electric ignitor or a propane pilot light in case gas reaches the surface.
- D. If location is near any dwelling a closed D.S.T. will be performed.

The Vit

ger 6 6 1993

CONTROLS