

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-32295
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Christmas A
8. Well No. 4
9. Pool name or Wildcat Jalmat T-Y-SR
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3505.6' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Dallas McCasland
3. Address of Operator P.O. Box 206, Eunice, NM 88231	4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>West</u> Line and <u>1980</u> Feet From The <u>South</u> Line Section <u>23</u> Township <u>22South</u> Range <u>36East</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3505.6' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-29-93 TD 1800 hrs 3600'./ Mud up 3500' Circ to run 5 1/2". Drop Totco. POH, no picture. Chg out hyd. pump. POH. RU run 5 1/2" csg 24# J-55 LT&C 80 jts. Circ hole. 11-30-93 RU Howco. Pump 10 BFW, 500 sks Hal. Lite (12.5#) followed by 150 sks C1 C Neat (14.8#) @ 5 BPM w/2% CaCl, w/1/4# Flo seal. Circ 81 sks to pit. Plug down 0848 hrs w/2% KCL wtr. Csg landed @ 3602' w/6'KB. RR 1200 hrs 11-30-93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dallas McCasland TITLE Operator DATE 12/01/93

TYPE OR PRINT NAME Dallas McCasland TELEPHONE NO. 394-2553

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE DEC 03 1993

CONDITIONS OF APPROVAL, IF ANY: