

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries).

38. GEOLOGIC MARKERS

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
RUSTLER	0	950	REDBEDS	RUSTLER	950'	
SALADO	950	1150	ANHYDRITE	SALADO	1150'	
CASTILLE	1150	4500	SALT, ANHYDRITE	CASTILLE	4500'	
DELAWARE	4500	4820	ANHYDRITE	DELAWARE	4820'	
BONE SPRING	4820	8763	LIMESTONE, SHALE, SANDSTONE	BONE SPRING	8763'	