		-				
Submit 3 Copies To Appropriate District	State of New Mexico			Form C-	1	
Office D strict (Energy, Minerals and Natural Resources		Revised March 25, 1999			
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.			
District II			30-025-32746			
811 South First, Artesia, NM 87210 District III			5. Indicate Type	of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410	Rd. Aztec. NM 87410 2040 South Pacheco		STATE			
District IV	Santa Fe, NM 87505		SIAIL			
2040 South Pacheco, Santa Fe, NM 87505	anta Fe, NM 87505		6. State Oil &	Gas Lease No		
		B-9652	Gas Lease NU.			
SUNDRY NOTICES AND REPORTS ON WELLS			7.			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					Í	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Warren Mckee B	rine Well		
PROPOSALS.) 1. Type of Well:						
	Other - Injection	e e sal				
2. Name of Operator			8			
Conoco Inc.			o 4			
3. Address of Operator			9. Pool name or Wildcat			
10 Desta Dr. Ste. 100w Midland, TX. 79705			BSW Salado (96173)			
· · · · · · · · · · · · · · · · · · ·			DSW Salado (90	175)		
10. Well Location			1			
Unit Letter N 33	0"feet from the So	uth line and19	980' feet from	n the West Line		
				· ·		
Section 2 Township 20S Range 38E NMPM LEA County						
10. Elevation (Show whether DR, RKB, RT, GR, ETC.)						
3568' GR						
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUB			SEQUENT RE	PORT OF:		
	PLUG AND ABANDON 📋	REMEDIAL WOR	к 🗆	ALTERING CASING	G	
	CHANGE PLANS	COMMENCE DRI		PLUG AND	Ø	
				ABANDONMENT	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
PULL OR ALTER CASING	MULTIPLE			XXX		
		CASING TEST AN CEMENT JOB	ŧn 🗋			
		OCMENT SOD				
OTHER:	·	OTHER:				
11. Describe proposed or complete	d operations. (Clearly state all pe	rtinent details, and give	e pertinent dates in	cluding estimated date		
of starting any proposed work).	SEE RULE 1103. For Multiple	Completions: Attach y	vellbore diagram of	proposed completion		
or recompilation.	•	•		proposed completion		
 RIH w/ C.I.B.P. to 1600' Set cibp Spotted plug #1 25sx. cement from 1600' to 1450' 						
• Circulated the hole w/ gelled brine mud (30sx. salt gel. 60bbls. brine.)						
• Spotted plug #2 (25sx. cement) from 500' to 350'						
• Spotted a 10sx. surface plug.						
Installed Dry-hole Marker and cleaned location.						
I						
hereby certify that the information above is true and complete to the best of my knowledge and belief.						

SIGNATURE Ben Figher - TITLE: FIELD SUPERVISOR	DATE 01/26/00
Type or print name: <u>BEN FISHER</u> (This space for State use) APPROVED BY	DATE 5 - // - 00
Conditions of approval	