

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-32777
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B1481
7. Lease Name or Unit Agreement Name: State N
8. Well No. 7
9. Pool name or Wildcat Eumant Yates 7 Rurs Qn
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
OXY USA WTP Limited Partnership 192463

3. Address of Operator
P.O. BOX 50250 MIDLAND, TX 79710-0250

4. Well Location
Unit Letter N : 840 feet from the South line and 1905 feet from the West line
Section 2 Township 22S Range 36E NMPM County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

STATE N-7

NOTIFY NMOCD OF INTENT TO P&A 12/27/00. MIRU PU 12/28/00, RDWH, NU BOP. RIH & SET CIBP @ 3503', CIRC HOLE W/ 9.5#MLF, SPOT 25sx CMT, WOC. RIH & TAG @ 3187', POOH TO 2876', SPOT 25sx CMT. POOH TO 1612', SPOT 25sx CMT, WOC. RIH & TAG CMT @ 1360'. POOH TO 442', SPOT 60sx CMT TO SURFACE. RDPU 12/29/00. DUG OUT CELLAR, CUT OFF WH & ANCHORS, INSTALL DRY HOLE MARKER, CLEAN LOCATION, WELL P&A'D.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE REGULATORY ANALYST DATE 3/22/01

Type or print name DAVID STEWART Telephone No. 915-685-5717

(This space for State use)

APPROVED BY GARY W. WINK TITLE OC FIELD REPRESENTATIVE II / STAFF MANAGER DATE FEB 25 2003

Conditions of approval, if any:

GWV