

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time, tool open, flowing and shut in pressures, and recoveries).

FORMATION

TOP

BOTTOM

DESCRIPTION, CONTENTS, ETC.

38. GEOLOGIC MARKERS

NAME	MEAS. DEPTH	TOP
		TRUE VERT. DEPTH
Yates	2691	+836
Seven Rivers	2983	+544
Queen	3538	-11
Penrose	3681	-154
Grayburg	3862	-335
San Andres	4084	-557
Glorieta	5341	-1814
Blinebry Mkr	5794	-2267
Tubb Mkr	6368	-2841
Drinkard	6625	-3098