

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240  
DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210  
DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 33028
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B 2656
7. Lease Name or Unit Agreement Name	Hardy 36 State
8. Well No.	21
9. Pool name or Wildcat	South Cass Strawn/Hardy Simp/Ellen

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> OTHER	
2. Name of Operator Conoco Inc.	
3. Address of Operator 10 Desta Dr. Ste 100W, Midland, Tx., 79705-4500	
4. Well Location Unit Letter <u>L</u> <u>1980</u> Feet From The <u>South</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>20S</u> Range <u>37E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3491'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER Downhole Commingle <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-2-98: Move in and rig up. NU BOP. SION. NU BOP, unset packer, SION.  
2-3-98: Bled casing down. Hot oil tubing, TOO H w/tbg & pkr, RIH w/retrieving head, SION.  
2-4-98: Finished RIH w/tbg, latched on to RBP, released, POOH w/tbg & RBP, RIH w/production tubing.  
2-5-98: Bled casing down. Pin failure-dropped tbg in hole, fished, POOH w/tbg fish. SION.  
2-6-98: Finish laying tbg down, RIH w/new tbg. SION.  
2-9-98: Finish picking up tbg, ND BOP, UP WH, RIH w/pump & rods, SION.  
2-10-98: Finish running rods, seat pump, load & test to 500#, clean location. 2 7/8" tubing set @ 10,374', tubing anchor @ 7590', 2 7/8" OEMA @ 10,408', pump @ 10,346-10,376', well put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Regulatory Agent DATE 3-10-98

TYPE OR PRINT NAME Ann E. Ritchie TELEPHONE NO. 915 684-6381

(this space for State Use)

APPROVED BY ORIGINAL SIGNED BY CHRIS WILLIAMS TITLE DISTRICT SUPERVISOR DATE 3-10-98

CONDITIONS OF APPROVAL, IF ANY: