

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 33277
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B 1534
7. Lease Name or Unit Agreement Name	State J2
8. Well No.	17
9. Pool name or Wildcat	Eumont Yates 7 Rvrs Qn (Pro Gas)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> OTHER <u>Injection</u>	2. Name of Operator Conoco Inc.
3. Address of Operator 10 Desta Dr. Ste 100W, Midland, Tx., 79705-4500	4. Well Location Unit Letter <u>I</u> <u>1340</u> Feet From The <u>South</u> Line and <u>990</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>22S</u> Range <u>36E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, R&B, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input checked="" type="checkbox"/> Pull rods, tubing & acidize	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work/SEE RULE 1103.)
11-9-98: POOH w/rods, GBIH w/fish, catch rods & POOH w/rods & pump, layed down rods for junk. SION.
11-10-98: Scan o log tubing, inspect, prep to acidize.
11-11-98: Pumped acid in 3 stages, starting from bottom perfs 12 bbls of acid w/ 12 bbls of flush. POOH w/tubing & installed pump, go back in hole and landed SN @ 3490', swabbed well. Prep to run new pump.
11-12-98: Go in hole with rods & pump, put well back on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE Ann E. Ritchie TITLE Regulatory Agent DATE 12-14-98
TYPE OR PRINT NAME Ann E. Ritchie TELEPHONE NO. 915 684-6381

(this space for State Use)
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY