CONDITIONS OF APPROVAL, IF ANY

State of New Mexico y, Minerals and Natural Resources Department E

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088	WELL API NO. 30-025-33284			
ta Fe, New Mexico 87504-2088				
	5. Indicate Type of Lease	[

DISTRICT II	DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III		30-025-33284				
			5. Indicate T	ype of Lease STATE X	FEE _		
1000 Rio Brazos Rd.,	, Aziec, NM 87410				6. State Oil &	k Gas Lease No.	
	011111111111111111111111111111111111111				mmm	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	mm.
(DO NOT LIKE TH	SUNDRY NOTICE	ES AND FIEPORTS C	N W	ELLS			
(50 101 035 14	IIS FORM FOR PHOPO DIFFERENT DESERVA	DSALS TO DRILL OR TO I	DEEPE EAD D	N OR PLUG BACK TO A	7. Lease Nan	e or Unit Agreement Name	
•		1) FOR SUCH PROPOSAL		Evital (
1. Type of Well:			<u> </u>		Sta	ite CC 16	
MET	ONS X	OTHER				100 10	
2. Name of Operator					8. Well No.		
Conoco, 1	inc.				b. Well No.	1	
3. Address of Operat	or	(915) 684-	-638	1 / 686-5424	9. Pool name	or Wildcat	
10 Desta	Drive, Suite	100W, Midland,			Wei	r Blinebry	
4. Well Location							
Unit Letter	C:330	Feet From The No	rth	Line and 2080	Feet F	rom The West	Line
		 					
Section	16	Township 20-S	R	ange 37-E N	IMPM	Lea	County
				DF, RKB, RT, GR, etc.)			
			<u>3533</u>			<u> </u>	
11.	Check App	propriate Box to Ind	icate	Nature of Notice, Re	port, or Oth	ner Data	
NO	TICE OF INTEN				-	REPORT OF:	
			_	0050	LGOLITI	TILI OITI OI .	_
PERFORM REMEDIA	L WORK	PLUG AND ABANDON		REMEDIAL WORK		ALTERING CASING	
EMPORARILY ABAN	IDON	CHANGE PLANS		COMMENCE DRILLING	OPNS.	PLUG AND ABANDON	MENT [
PULL OR ALTER CAS	ING			CASING TEST AND CEN	AENT JOB		
OTHER: P	erf & Product:	ion	X	OTHER:			X
12 Damba Barrada				<u> </u>			
work) SEE RULE	or Completed Operations (1103.	(Clearly state all pertinent de	lails, an	d give pertinent dates, includi	ng estimated date	e of starting any proposed	
6-24-96:	Shot fluid 1	evel. blew well	dowr	n. POH w/ rods &	C Dump	Porforato Plimal	L
	w/2 spf @ 560	01 - 5616'.	dow.	i. Ion w/ lous (a pump.	reflorate bline	Dry
6-25-96:	Finish going	in hole, set RB	P @	5800', set packe	er @ 5500	'. Acidize Blin	ehrv
	(5601 - 5616)) w/2000 gal 15%	11/01			· MCIGIZE DIII	eury
6-26-06		, , , , , , , , , , , , , , , , , , , ,		bolate Jubi	1 W/?		
6-26-96 -	Swabbing		F=	roma a a	/		
6-30-96:							
7-1-96:	Perforate Bli	inebry w/ 1 JSPF	as	follows:			
	5616 - 5660'.	Frac w/47,000	gal	s Spectra, 82,14	0# 16/30	sand.	
7-2-96:							
, 2 90.	wan broductio	m LDg. EO 2002	. W	ell put on produ	iction.		
		pen , 618					
		any Blok	de	mod in Ju	10 /17	1115	
I hereby certify that the self-	1111						
I have y used y use use yet		emplete to the best of my knowled	age mod b	d≥ .			
SIGNATURE CASO	Lulahi		1111_	Regulatory	Agent	9-9-96	<u> </u>
	•						
TYPE OR PRINT NAME		Yabasasasasas				TELEPHONE NO	
(Thus space for State Use)	()						
		TELL TRUE I				ى ئا <u>ئۇ</u> ئ اشە لىدا بىسى	# 4 ·
A BREE CILIED BY			_			OSTIET	55.4
APPROVED BY			- TTTLE			DATE	

2A Monument Tuhh