

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-33387
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name Diamond 34 State
Well No. 1
Pool name or Wildcat SWD - Bell Canyon - Cherry Canyon

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD	
Name of Operator Pogo Producing Company	
Address of Operator P. O. Box 10340, Midland, TX 79702-7340	
Well Location Unit Letter <u>N</u> : <u>990</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>West</u> Line Section <u>34</u> Township <u>22S</u> Range <u>33E</u> NMPM <u>Lea</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3576 GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

¹²Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

09/07/99 Perf 6102'-26', 6046'-84' @ 4 JSPF .38" dia holes. Perf 5980'-6002' @ 2 JSPF .38" dia holes.

09/08/99 Set RBP @ 6150' & test to 3000# ok. Acdz w/ 1500 gals 7-1/2% NeFe & 750# salt. Latch onto RBP & release. PUH to 5871' and set RBP - test to 3000# ok. Perf 5560'-90' @ 2 JSPF.

09/09/99 Acdz 5560'-90' w/ 1000 gals 7-1/2% NeFe. Frac w/ 252,000# 16/30 sand.

09/10/99 NU BOP. Circ hole clean. Latch onto RBP, release & TOH.

09/11/99 GIH w/ CIBP & set @ 5930'. Perf 5722'-48', 5698'-5714', 5650'-78', 5526'-60', 5435'-60' @ 4 JSPF & 5560'-90' @ 2 JSPF.

09/14/99 ND BOP. NU WH. Set pkr @ 5406'. Put well on injection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cathy Tomberlin TITLE Operations Tech DATE 09-15-99
TYPE OR PRINT NAME Cathy Tomberlin TELEPHONE NO. (915)685-8100

(This space for State Use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

APR 19 2002
DATE

