

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
				Yates	2730	+ 817
				Seven Rivers	2989	+ 558
				Queen	3543	+ 4
				Penrose	3703	- 156
				Grayburg	3876	- 329
				San Andres	4095	- 548
				Glorieta	5375	- 1828
				Blinebry Mkr	5833	- 2286
				Tubb Mkr	6359	- 2812
				Drinkard	6627	- 3080