FORM 3160-5 UN	STATES	FORM APPROVED
(June 1990) DEPARTMENT	OF THE INTERIOR N.M. OIL CONS.	DIVISISüdget Bureau No. 1004-0135
BUREAU OF LA	ND MANAGEMENT 1625 N. French	Dr. Expires: March 31, 1993
	Hobbs, NM 882	AcLease Designation and Serial No.
SUNDRY NOTICES AND REPO	RTS ON WELLS	NM 43739
Do not use this form for proposals to drill or		6. If Ind an, Allottee or Tribe Name
Use "APPLICATION FOR PE	RMIT -" for such proposals	NA
SUBMIT IN T	RIPLICATE	7. If Unit of CA, Agreement Designation NA
1. Type of Well		
Oil Gas		8. Well Name and No.
X Well Well Other	-	NMFU Federal #1
		P. APT Well No.
2. Name of Operator		30-025-33836
Falcon Creek Resources, Inc.		10. Field and Pool, or Exploratory Area Abo
3. Address and Telephone No.	0 80202 0621 (202) 675 0007	11. County or Parish, State
621 17th Street, Suite 1800, Denver Co 4. Location of Well (Footage, Sec., T., R., M., or Survey		11. County of Parish, State
Sec. 23, T20S, 38E	Description	
		Lea County NM
12. CHECK APPROPRIATE E	BOX(es) TO INDICATE NATURE OF NOTICE	, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE O	FACTION
X Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
—	X Other Additional Abo perfs	Dispose Water
	(Note: Report results of multiple completion Completion or Recompletion Report an	
13. Describe Proposed or Completed Operations (Clea	I ny state all pertinent details, and give pertinent dates,	Including estimated date of starting any proposed
work. If well is directionally drilled, give subsurface	locations and measured and true vertical depths for a	all markers and zones pertinent to this work.)*
Work is proposed to start 4-11-00 1. Perforate Abo from 7510-30, 7605-	25 7640 50 7750-60 4 spf 44 holes	
	bo perfs, Blinebry & Tubb formation with p	backer set at 7450
	with 2400 gallons 20% HCL and 1400 gall	
4. Swab test and evaluate		
5. Put on production for testing & con	nmingling info.	
	perfs and with Blinebry & Tubb formations	5.
-		
14. I hereby certify that the foregoing is true	e and correct	
Signed Hunse Luces	Title Manager of Operatio	Date 04/06/00
(This space for Federal or State office use)		E600
Approved by (ORIG. SGD) GAFIY GOU	<u>IRLE</u> Title	Date <u>ADR 1 4 2939</u>
Conditions of approval, if any:		
Title 18 I S.C. Section 1001 makes it a stime for any nors	on knowingly and willfully to make to any department or age	ncy of the United States andy false, fictitious or fraudulent
statements or representations as to any mater within its juri		

5

Et :01 ∀ 01 888 000 1000 01 6500 01 000 2000 01 6500 01 000 1000 01 000 01 000

EENIE0EL

(June 1990) DEPARTMENT O BUREAU OF LAN SUNDRY NOTICES AND REPOR Do not use this form for proposals to drill or the second	to deepen or reenter a different reservoir.	Eudget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM 43739 6. If Indian, Allottee or Tribe Name
	RMIT -" for such proposals	NA 7. If Unit or CA, Agreement Designation
SUBMIT IN T	RIPLICATE	NA
	-	8. Well Name and No. NMFU Federal #1 9. APT VietT No. 30-025-33836
Falcon Creek Resources, Inc.		10. Field and Pool, or Exploratory Area
3. Address and Telephone No.		Abo
621 17th Street, Suite 1800, Denver CC 4. Location of Well (Footage, Sec., T., R., M., or Survey Sec. 23, T20S, 38E		11. County or Parish, State Lea County NM
	OX(es) TO INDICATE NATURE OF NOTICE	
TYPE OF SUBMISSION	TYPE O	FACTION
 Isolate new Abo perfs from existing A Isolate Abo, Blinebry, and Tubb perfs Acidize new Abo perfs with 1125 gall Swab test & evaluate 	ocations and measured and true vertical depths for a om 7295-7310 & 7365-7395 w/ 4spf 44 ho Abo perf with RBP at 7450' s with packer set at 7200' ons of 20% HCL and 6750 gallons of 289	d Log form.) Thcluding estimated date or starting any proposed Ill markers and zones pertinent to this work.)*
 Put on production for testing & comm 8. Intend to commingle new Abo perfs of 14. I hereby certify that the foregoing is true 	with already commingled Blinebry and Tu and correct	
Signed Lune Lune	Title Manager of Operation	ns Date 04/05/00
(This space for Federal or State office use) Approved by <u>(ORIG. SGD.) DAVID Has</u> Conditions of approval, if any:	HETROLEUM ENGINI	EER APR 1 2 2000
 Downhole Commingling Must Be Approve By New Mexico Oil Conservation Division And This Office. 	d Ifully to make to any department or agen (NMOCD) tions on Reverse Side	cy of the United States andy false, fictitious or fraudulent

GWW	
-----	--

う レ

SECEIVED

Partao HPAsoa State of China Sources



District I Energy, Minerals and Natural Resources 1623 N. French Dr., Hobbs, NM 88240 Difference Dr., Hobbs, NM 88240 District II 2040 South First, Artesia, NM 88210 1000 Rio Brazos Rd., Aztee, NM 87410 Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS South Pacheco, Santa Fe, NM 87505 Co Not USE This FOR HOP ROPOSALS to DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 7. Lease Name or Unit Agreement Name Oil Well Gas Well Other 8. Well No. 1. Type of Well: Oil Construct Ison for PERMIT" (FORM C-101) FOR SUCH NMFU Federal 3. Address of Operator S. Well No. 1 3. Address of Operator South Ison for the South Ison for PERMIT" (FORM ther DR, RKB, RT, GR, etc.) 9. Pool name or Wildcat East Warre Tubb, Blinebry Oil & Gas 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3560 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3561 MPMM 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	Submit 3 Copies To Appropriate District	State of New Mexico	Form C-1
Damaid 330-025-33335 Bisob Fit, Arma, NM 9210 OIL CONSERVATION DIVISION Basoliti 2040 South Pacheco Damaid Status Processon Damaid Damaid Damaid Status Processon Damaid Damaid	District	gy, Minerals and Natural Resources	Revised March 25, 1
11) Sock THIS Strict Arriver Field Strict Processor State Strict Processor Prophysteresteper Strict Processor Strict Processor Stri			1
Data cliii 2040 South Pacheco Santa Fe, NM 87505 Santa Fe, NM 87505 Of No Packeo, Santa Fe, NM 87505 Subsche Adates, Markeo, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 6. State Oil & Gas Lease No. COPORTUSE THE SERVOIL, USE "APPLICATION FOR PERMIT" (FORM C-10) FOR SUCH 7. Lease Name or Unit Agreement Name Operator 1. Type of Well: Other 8. Well No. 2. Name of Operator 6.11 /th Street Suite 1800 Deriver C0 80293 9. Pool name or Wildeat East Warree 3. Address of Operator 6.60 feet from the South line and 650 feet from the East line Section 23 Township 20S Range 38E NMPM County Lea Well Location 10. Elevation Show whether DP, RK& RT, GR, etc.) SUBSEQUENT REPORT OF: Section 23 Township 20S Range 38E NMPM County Lea State PORT OF: SUBSEQUENT REPORT OF: PERCORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: PULL OR ALTER CASING MULIPILE COMMENCE DRILLING OFNS PLUG AND ABANDON COMPLETION CENTRE PROFT ARD CASING TEST AND CENTRE ARD OTHER: County FLE OTHER: Remove CIEP DATE Z/23/C		CONSERVATION DIVISION	
Data Statu Santa Fe, NM 87305 6. State OIL & Gas Lease No. 2008 Subtrackee, sand Fe, NM 87305 6. State OIL & Gas Lease No. 6. State OIL & Gas Lease No. 2018 Subtrackee, sand Fe, NM 87305 6. State OIL & Gas Lease No. 7. Lease Name of Unit Agreement Name DIFFERENT RESERVOR. USE "APPLICATION FOR FERMIT" (FORM C-101) FOR SUCH NEOROSALS.) 7. Lease Name of Unit Agreement Name OPPORT USE THE FORM FOR FORM FERMIT" (FORM C-101) FOR SUCH NEOROSALS.) 7. Lease Name of Unit Agreement Name NEOROSALS.) 2. Name of Operator 521 17th Street Suite 1800 Denver CD 80293 9. Pool name or Wildcat East Werre Salt 3. Address of Operator 521 17th Street Suite 1800 Denver CD 80293 9. Pool name or Wildcat East Werre Salt 3. Comments of the South line and	District III	2040 South Pacheco	
2000 South Packeos, Same F, NM 87:05 0. Solar Coll South State FNO. 2000 Fulls THIS FORM FOR PROPORALS TO DALLL OR TO DEPEND OR PLACE BACK TO A DEPEND FOR PROPORALS TO DALLL OR TO DEPEND OR PLACE BACK TO A DEPEND FOR FORM FOR PROPORALS TO DALLL OR TO DEPEND OR PLACE BACK TO A DEPEND FOR FORM FOR PROPORALS TO DALLL OR TO DEPEND OR PLACE BACK TO A DEPEND FOR PROPORALS TO DALLL OR TO DEPEND OR PLACE BACK TO A DEPEND FOR FORM FOR PROPORALS TO THE PLACE TOOM FOR FREMENT' (FORM C-101) FOX SUCH 7. Lease Name of Unit Agreement Name NMFU Federal 1. Type of Well Oil Well Imme of Operator 8. Well Imme of Wells 1 3. Address of Operator Fall Con Creek Resources Inc. 9. Pool name of Wilden East Marrie 1 4. Well Location Unit Letter		Santa Fe. NM 87505	
(DO NOT USE THIS FOR MOR PROPOSALSTO DERLLOR TO DEFENSIOR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH NMFU Federal 1. Type of Well: Oil Well Totas Well Cas Well Other Other 8. Well No. 2. Name of Operator 621 17th Street Suite 1800 Derver C0 80293 9. Pool name of Wildeat LaSt Warre Tubb, Blinebry Oil & Gas 4. Well Location 9. Pool name of Wildeat LaSt Warre Tubb, Blinebry Oil & Gas 5. Address of Operator 621 17th Street Suite 1800 Derver C0 80293 9. Pool name of Wildeat LaSt Warre Tubb, Blinebry Oil & Gas 6. Well Location 10. Elevation (Now whether DR, RKB, RT, GR, etc.) 10. Elevation (Now whether DR, RKB, RT, GR, etc.) 9. Section 23 Township 20S Range 38E NMPM County Lea 9. Congregative Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: 9. PULL OR ALTER CASING MULTIPLE COMMENCE DRILLING OPNS PLUG AND ABANDONMENT 0THER: COMPLETION OTHER: Remove Clipp PLUG AND ABANDONMENT 10. Elevation S. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of ataring any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of ataring any proposed work). SEE RULE 1103. For Multiple Completion: Atta			6. State Ult & Gas Lease No.
(DO NOT USE THE FORM FOR PROPOSALS TO DERILLOR TO DEPEND OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS) NMFU Federal 1. Type of Well: Oil Well G Gas Well C Other 0. 1 2. Name of Operator Gal 17th Street Suite 1800 Deriver C0 80293 9. Pool name of Wildeat LaSt Warre Tubb, Blinebry Oil & Gas 4. Well Location 9. Pool name of Wildeat LaSt Warre Tubb, Blinebry Oil & Gas 4. Well Location 10. Elevation (Show whether DR, RKB, RT GR, etc.) 10. Elevation (Show whether DR, RKB, RT GR, etc.) 3. FOR CE OF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING MULTIPLE COMMENCE DRILLING OPINS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION COMPLETION OTHER: COMPLETION OTHER: Remove CIEP PLUG AND ABANDONMENT 10. Elevation stove is true and complete to the best of my knowledge and bellef. Not E831' 11. Otheck Appropriate Box to Indice to the best of my knowledge and bellef. DATE 2/23/c 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of stating any proposed work). SEE RULE 1103. For Multiple Completion: Attach wellbore d	SUNDRY NOTICES AND	REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
1. Type of Well: Other 2. Name of Operator Falcon Creek Resources Inc. 1 3. Address of Operator 9. Pool name or Wildcat EaSt Warree 621 17th Street Suite 1800 Denver C0 80293 Tubb., Blinebry 011 & Gas 4. Well Cocion Unit Letter P. 660 feet from the South line and 660 feet from the East kin Section 23 Township 20S Range 38E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3567 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND BANDON COMMENCE DRILLING OPNS. ALTERING CASING PULL OR ALTER CASING MULTPLE COMPLETION CEMENT JOB BANDONMENT 0THER: OTHER: OTHER: OTHER: BANDONMENT BANDONMENT 12. Describe proposed or completed operations. (Clearly state all periment details, and give pertiment dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellfore diagram of proposed completion or recompilation. 1.) 2/18/99 Drill out CLEP from 6305-6305. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping <	(DO NOT USE THIS FORM FOR PROPOSALS TO DR DIFFERENT RESERVOIR. USE "APPLICATION FOR	ILL OR TO DEEPEN OR PLUG BACK TO A	
2. Name of Operator Falcon Creek Resources Inc. 8. Well No. 3. Address of Operator 521 17th Street Suite 1800 Denver C0 80293 9. Pool name or Wildcat East Warre 521 17th Street Suite 1800 Denver C0 80293 4. Well Letter P 660 _feet from the	1. Type of Well:		
Falcon Creek Resources Inc. 1 3. Address of Operator 9. Pool mame or Wildeat East Warree 621 17th Street Suite 1800 Denver C0 80293 9. Pool mame or Wildeat East Warree 4. Well Location 1 Unit Letter		her	
3. Address of Operator 9. Pool name or Wildcat East Warre 621 17th Street Suite 1800 Denver C0 80293 9. Pool name or Wildcat East Warre 4. Well Location Unit Letter P 660 feet from the Sate Strength 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3567 GR 386 NMPM Coung Lea 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: PEFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PULL OR ALTER CASING CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: Remove CISP 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompliation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/20/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping TITLE Senior Engineer DATE 2/23/C Type or print name Joe H. Cox Jr. Telephone No.303-675-00(2. Name of Operator Falcon Creek	Resources Inc.	8. Well No.
Unit Letter P 660 feet from the South line and 660 feet from the East line Section 23 Township 20S Range 38E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3567 GR County Lea NOTICE COF INTENTION TO: SUBSEQUENT REPORT OF: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT 12. Describe proposed or completed operations. (Clearly state all perinent details, and grouposed completion or recompilation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 1.) 2/18/99 Prill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping TITLESenior Engineer DATE 2/23/c Type or print name Joe H. Cox Jr. Telephone; No.303-675-00 <	3. Address of Operator		9. Pool name or Wildcat East Warre Tubb, Blinebry Oil & Gas
Section 23 Township 20S Range 38E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3567 GR 11. 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PUUL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT PUUL OR ALTER CASING MULTIPLE CASING TEST AND ABANDONMENT 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions. Attach wellbore diagram of proposed completion or recompilation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/20/99 Well pumping Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE DATE 2/23/c Type or print name Joe H. Cox Jr. THELE Senior Engineer DATE 2/			
Section 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3567_GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OTHER: OTHER: OTHER: Remove CIBP 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompliation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping	Unit Letter P : 660		660 feet from the East line
3567 GR 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND BANDON TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION COTHER: OTHER: COMPLETION OTHER: Remove CISP 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping	Section 23	Township ^{20S} Range ^{38E}	NMPM County Lea
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON BANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND BANDONMENT BANDONMENT 0THER: OTHER: OTHER: Remove CIBP CASING Test AND Completions: ABANDON 12. Describe proposed or completed operations. (Clearly state all periment details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping TTTLE_Senior Engineer DATE 2/23/c Type or print name Joe H. Cox Jr. Telephone No.303-675-00 (This space for State use) Other State use) Telephone No.303-675-00			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT OTHER: OTHER: OTHER: CASING TEST AND CEMENT JOB Interview of starting any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB PLUG AND ABANDONMENT OTHER: OTHER: OTHER: CASING TEST AND CEMENT JOB Image: Completed operations. 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompliation. 1. 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping DATE 2/23/C Thereby certify that the information above is true and complete to the best of my knowledge and belief. DATE 2/23/C SIGNATURE DOT H. Cox Jr. TTTLE Senior Engineer DATE 2/23/C Type or print name Joe H. Cox Jr. Telephone No.303-675-00			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: Remove CIBP 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping			
PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB ABANDONMENT OTHER: OTHER: Remove CIBP 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	PERFORM REMEDIAL WORK 🔲 PLUG A		
COMPLETION CEMENT JOB OTHER: OTHER: Remove CIBP 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Jee MC22 TYpe or print name Joe H. Cox Jr. Type or print name Joe H. Cox Jr.	TEMPORARILY ABANDON 🔲 CHANGI	E PLANS COMMENCE DF	
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 1.) 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2.) 2/19/99 Run pump with rods. Hung well on. 3.) 2/20/99 Well pumping I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE			AND
 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 2/18/99 Drill out CIBP from 6305-6306. Run tubing to 7004 SN at 6831' 2/19/99 Run pump with rods. Hung well on. 2/20/99 Well pumping 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE			
SIGNATURE Let al Control TTTLE_Senior Engineer DATE 2/23/c Type or print name Joe H. Cox Jr. Telephone No.303-675-00 (This space for State use) Telephone No.303-675-00	OTHER:		
SIGNATURE Let Clear TITLE Senior Engineer DATE 2/23/c Type or print name Joe H. Cox Jr. Telephone No.303-675-0 (This space for State use) Telephone No.303-675-0	OTHER: 12. Describe proposed or completed operation of starting any proposed work). SEE RUD or recompilation. 1.) 2/18/99 Drill out CIBF	ons. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Atta P from 6305-6306. Run tubing	give pertinent dates, including estimated da ach wellbore diagram of proposed completio
SIGNATURE Let Clear TITLE Senior Engineer DATE 2/28/c Type or print name Joe H. Cox Jr. Telephone No.303-675-0 (This space for State use) Telephone No.303-675-0	OTHER: 12. Describe proposed or completed operation of starting any proposed work). SEE RUD or recompilation. 1.) 2/18/99 Drill out CIBF 2.) 2/19/99 Run pump with	ons. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Atta P from 6305-6306. Run tubing	give pertinent dates, including estimated dat the wellbore diagram of proposed completion
SIGNATURE Let Clear TITLE Senior Engineer DATE 2/28/c Type or print name Joe H. Cox Jr. Telephone No.303-675-0 (This space for State use) Telephone No.303-675-0	OTHER: 12. Describe proposed or completed operation of starting any proposed work). SEE RUD or recompilation. 1.) 2/18/99 Drill out CIBF 2.) 2/19/99 Run pump with	ons. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Atta P from 6305-6306. Run tubing	give pertinent dates, including estimated dat the wellbore diagram of proposed completion
Type or print name Joe H. Cox Jr. Telephone No.303-675-00 (This space for State use)	OTHER: 12. Describe proposed or completed operation of starting any proposed work). SEE RUD or recompilation. 1.) 2/18/99 Drill out CIBF 2.) 2/19/99 Run pump with	ons. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Atta P from 6305-6306. Run tubing	give pertinent dates, including estimated dat the wellbore diagram of proposed completion
(This space for State use)	OTHER: 12. Describe proposed or completed operation of starting any proposed work). SEE RUN or recompilation. 1.) 2/18/99 Drill out CIBF 2.) 2/19/99 Run pump with 3.) 2/20/99 Well pumping	ons. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Atta P from 6305-6306. Run tubing rods. Hung well on.	give pertinent dates, including estimated dat ich wellbore diagram of proposed completion to 7004 SN at 6831'
(This space for State use)	OTHER: 12. Describe proposed or completed operation of starting any proposed work). SEE RUN or recompilation. 1.) 2/18/99 Drill out CIBF 2.) 2/19/99 Run pump with 3.) 2/20/99 Well pumping I hereby certify that the information above is t	ns. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Atta of from 6305-6306. Run tubing rods. Hung well on.	give pertinent dates, including estimated dat ich wellbore diagram of proposed completion to 7004 SN at 6831'
APPPROVED BY TITLE DATE	OTHER: 12. Describe proposed or completed operation of starting any proposed work). SEE RUD or recompilation. 1.) 2/18/99 Drill out CIBF 2.) 2/19/99 Run pump with 3.) 2/20/99 Well pumping I hereby certify that the information above is the SIGNATURE SIGNATURE	rue and complete to the best of my knowle	l give pertinent dates, including estimated dat ich wellbore diagram of proposed completion to 7004 SN at 6831' dge and belief. ineer DATE $2/23/c$
	OTHER: 12. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompilation. 1.) 2/18/99 Drill out CIBF 2.) 2/19/99 Run pump with 3.) 2/20/99 Well pumping I hereby certify that the information above is to SIGNATURE Type or print name Joe H. Cox Jr	rue and complete to the best of my knowle	give pertinent dates, including estimated dat ich wellbore diagram of proposed completion to 7004 SN at 6831' edge and belief. ineer DATE $2/23/c$ Telephone No.303-675-00