Form 3 160-5 (June 1990)	DEPARTMENT	D STATES OF THE INTERIOR ND MANAGEMENT	90 Et :- Kobbs, MM		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 3 1 ,1993 5. Lease Designation and Serial No.
SUNDRY NOTICES AND REPORTS ON WELLS					LC 031621B
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals					5. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICA TE					7. If Unit or CA, Agreement Designation
2. Name of Operator					Well Name and No.
Conoco Inc					Britt B #33
3. Address and Telephone No.					30-025-33907
10 DESTA DR. STE. 100W, MIDLAND, TX. 79705-4500 (915) 686-5580					0. Field and Pool, or Exploratory Area
4. Location of Well (Footage. Sec., T. R. M. or Survey Description)					Eunice Monument (G/SA)
760' FNL & 1980' FWL, Sec. 15, T20S, R37E, C					
	PPROPRIATE BOX(s)	TO INDICATE NATU	JRE OF NOTICE, F	REPORT	Lea, NM , OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION				CTION	<u></u>
Notice of	Intent	Abandonn			Change of Plans
Subsequer	nt Report	Recomplet	Back		New Construction Non-Routine Fracturing
Final Aba	ndonment Notice	Casing Re Altering C Other	-	est	Water Shut-Off Conversion to Injection Dispose Water Note: Report results of multiple completion on WeB
It is proposed to perfo attached recommenda	orm a Casing Integrity Test	on this well in preparati	pertinent to this work.)*	oorary abai	APPROVED
14. I hereby cartify that the fo	1 1	Reesa R. W	ilkes gulatory Assistant	BURE	PETER W. CHESTER JUL 8 1999 AU OF LAND MANAGEMENT SWELL RESOURCE AREA Date06/23/99
(This space for Federal or	r State office use)		<u>×</u>		
Approved by Conditions of approval if	any:	Title			Date

BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, FILE ROOM

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

<u>Britt B #33</u> 30-025-33907 Recommendation to Temp. Abandon

This well is currently inactive. It is recommended that the well be temporarily abandoned in order to evaluate possible deepening to the Blineberry zone.

- 1. POOH w/ rods and tubing.
- 2. Make scraper run inside 5.5", 15.5# casing to 4168'.
- 3. Set Cast Iron Bridge Plug w/in 50' of top of perfs @ 4118', spot 35' cmt on top of CIBP.
- Circulate Casing with inhibited packer fluid.
 BLM
 Pressure test casing to 500# for 30 minutes. Give CCD 24 hrs notice prior to pressure test.

Mic