

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof, cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut in pressures, and recoveries):

FORMATION	TOP		BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
						MEAS. DEPTH	TRUE VERT. DEPTH
Yates	2850'		2900'	Water & moveable HC	Seven Rivers Queen Penrose Grayburg San Andres Glorietta Blinebry Marker Tubb	3019	+517
Seven Rivers Grayburg/San Andres	2985		3030	Water & moveable HC		3582	-46
	3250		3350	Stringers - water & moveable HC		3732	-192
	4085'		5250	"		3913	-377
	5400'		5500	"		4136	-600
Glorieta	5530		5630	"		5404	-1868
	5650		5690	"		5894	-2358
Blinebry	5750		5845	"		6414'	-2878'
	5850		5920	"			
Tubb	5980		6090	"			
	6115		6208	"			
	6246		6410	"			
	6600		6772	"			