

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof, cored intervals, and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut in pressures, and recoveries)

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	
			Mea. Depth	Sub Sea Depth
Drinkard	6780'	6940'	Oil, gas & water	
Tubb	6578'	6690'	Probable oil, gas & water based on analogy to logs	
Blinebry	5970'	6160'		

38.

GEOLOGIC MARKERS

NAME	MEAS. DEPTH	TOP	
		TRUE	VERT. DEPTH
Rustler	2767'	811	
Yates	3125'	453	
Seven Rivers	3687'	109	
Queen	3806'	228	
Penrose	3952'	374	
Grayburg	4172'	594	
San Andres	5531'	1953	
Glorieta	5992'	2412	
Blinebry(NMOCD)	6472'	2894	
Tubb (Marker)	6770'	3192	
Drinkard	7030'	3452	
Abo	-	-	
Wolfcamp	-	-	
Strawn	-	-	