to Appropriate District Office	Energy, Minerals and Natura	Mexico Il Resources Department		Form C 103 Revised 1-1-89
<u>DISTRICT</u> I P.O. Box 1980, Hobbs, NM S8240	HOBDS, NM S8240 OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO.	30 025 34794
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mex		5. Indicate Type o	f Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil& Gas	
( DO NOT USE THIS FORM FOR PR DIFFERENT RESE	TICES AND REPORTS ON N OPOSALS TO DRILL OR TO DEE RVOIR. USE "APPLICATION FOR C-101) FOR SUCH PROPOSALS.)	PEN OR PLUG BACK TO A	7. Lease Name or I	Jnit Agreement Name
1. Type of Well: Oil Well Well	OTHER			Hardy 36 State
2. Name of Operator Conoco Inc.	<u></u>	····	8. Well No.	27
3. Address of Operator 10 Desta Dr. Ste 100W, Midla	ind, Tx., 79705-4500		9. Pool name or W Not	
4. Well Location Unit Letter J 220	0 Feet From The Sour	th Line and16	50 Feet From	The <u>East</u> Lir
Section 36	Township 20S	e 516	NMPM	Lea County
///////////////////////////////////////	10. Elevation (Show who 3493' GR	ether DF, RKB. RT, GR, etc.)	/////////	
n. Check	Appropriate Box to Indica	ate Nature of Notice, R	eport, or Other	· Data
NOTICE OF IN			SEQUENT R	
	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GOPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB	
OTHER:	· · · · · · · · · · · · · · · · · · ·	OTHERHorizontal ho	ole	Looka kovij
			luding estimated date	of starting any proposed
12. Describe Proposed or Completed C work)SEE RULE 1103.	perations (Clearly state all pertinent d	etalis, and give pertinent dates, ind		starting any proposed
work)SEE RULE 1103. 2-2-01: Killed well. Tested equipm 2-3-01: Ran & set Smith Big Bore J surface. Rig down wireline. 3-5-01: Moved in, rigged up. Blew	ent. RIH with mill to 7775'. SI packer @ 7547', ran Scientific	ON. Drilling Gyro & smith orie	entaion survey too	l. Ran gyro from packer to
work)SEE RULE 1103. 2-2-01: Killed well. Tested equipme 2-3-01: Ran & set Smith Big Bore j surface. Rig down wireline.	ent. RIH with mill to 7775'. SI packer @ 7547', ran Scientific well down. Set test tank & tes ils slick water & 19,000 gals 20	ON. Drilling Gyro & smith orie t separator. Prep to flow w 0% NEFE HCL & 10,000 g	entaion survey too ell down/kill & ru gals 20% slick NE	<ol> <li>Ran gyro from packer to in production string. SION.</li> <li>FE HCL. Removed packer.</li> </ol>
work)SEE RULE 1103. 2-2-01: Killed well. Tested equipme 2-3-01: Ran & set Smith Big Bore p surface. Rig down wireline. 3-5-01: Moved in, rigged up. Blew 4-30-01: Ran logs. 5-1-01: Fraced Strawn w/25,170 ga 5-01: Pulling out of hole w/3 1/2" 5-4/11-01: Plow testing well. 5-24-01: RIH w/ESP equipment. Ho 5-25-01: Started ESP. 7-11-01: Production test @ 440 oil,	ent. RIH with mill to 7775'. SI packer @ 7547', ran Scientific well down. Set test tank & tes ils slick water & 19,000 gals 20 string. RIH w/production strin ooked up to flowline. SION. , 12 water and 917 gas.	ON. Drilling Gyro & smith orient t separator. Prep to flow w % NEFE HCL & 10,000 g ng. Displaced annulus. Set	entaion survey too ell down/kill & n gals 20% slick NE packer @ 7450'. J	<ol> <li>Ran gyro from packer to in production string. SION.</li> <li>FE HCL. Removed packer.</li> <li>Yested pkr to 1000#. SION.</li> </ol>
work)SEE RULE 1103. 2-2-01: Killed well. Tested equipme 2-3-01: Ran & set Smith Big Bore p surface. Rig down wireline. 3-5-01: Moved in, rigged up. Blew 1-30-01: Ran logs. 5-1-01: Fraced Strawn w/25,170 ga SION. 5-3-01: Pulling out of hole w/3 1/2" 5-4/11-01: Flow testing well. 5-24-01: RIH w/ESP equipment. H 5-25-01: Started ESP. 7-11-01: Production test @ 440 oil, Sundry filed to submit "Actual Wel	ent. RIH with mill to 7775'. SI packer @ 7547', ran Scientific well down. Set test tank & tes ils slick water & 19,000 gals 20 string. RIH w/production strin ooked up to flowline. SION. , 12 water and 917 gas. Il Profile'', performed 2-16-01.	ON. Drilling Gyro & smith orient t separator. Prep to flow w % NEFE HCL & 10,000 g og. Displaced annulus. Set C-102 previously submitte	entaion survey too ell down/kill & n gals 20% slick NE packer @ 7450'. J	<ol> <li>Ran gyro from packer to in production string. SION.</li> <li>FE HCL. Removed packer.</li> <li>Yested pkr to 1000#. SION.</li> </ol>
work)SEE RULE 1103. 2-2-01: Killed well. Tested equipme 2-3-01: Ran & set Smith Big Bore p surface. Rig down wireline. 3-5-01: Moved in, rigged up. Blew 4-30-01: Ran logs. 5-1-01: Fraced Strawn w/25,170 ga SION. 5-3-01: Pulling out of hole w/3 1/2" 5-4/11-01: Flow testing well. 5-24-01: RIH w/ESP equipment. He 5-25-01: Started ESP. 7-11-01: Production test @ 440 oil, Sundry filed to submit "Actual Well 1 hereby certify that the information above is the	ent. RIH with mill to 7775'. SI packer @ 7547', ran Scientific well down. Set test tank & tes ils slick water & 19,000 gals 20 string. RIH w/production strin ooked up to flowline. SION. 12 water and 917 gas. Il Profile'', performed 2-16-01.	ON. Drilling Gyro & smith orient t separator. Prep to flow w 0% NEFE HCL & 10,000 g ng. Displaced annulus. Set C-102 previously submitte and belief.	entaion survey too ell down/kill & n gals 20% slick NE packer @ 7450'. J	<ol> <li>Ran gyro from packer to in production string. SION.</li> <li>FE HCL. Removed packer.</li> <li>Tested pkr to 1000#. SION.</li> <li>mal logs submitted 8-20-01.</li> </ol>
work)SEE RULE 1103. 2-2-01: Killed well. Tested equipme 2-3-01: Ran & set Smith Big Bore p surface. Rig down wireline. 3-5-01: Moved in, rigged up. Blew 1-30-01: Ran logs. 5-1-01: Fraced Strawn w/25,170 ga SION. 5-3-01: Pulling out of hole w/3 1/2" 5-4/11-01: Flow testing well. 5-24-01: RIH w/ESP equipment. H 5-25-01: Started ESP. 7-11-01: Production test @ 440 oil, Sundry filed to submit "Actual Wel	ent. RIH with mill to 7775'. SI packer @ 7547', ran Scientific well down. Set test tank & tes ils slick water & 19,000 gals 20 string. RIH w/production strin ooked up to flowline. SION. 12 water and 917 gas. Il Profile'', performed 2-16-01.	ON. Drilling Gyro & smith orie t separator. Prep to flow w % NEFE HCL & 10,000 g og. Displaced annulus. Set C-102 previously submitte e and belief. TITLE Regulatory Agent	entaion survey too ell down/kill & n gals 20% slick NE packer @ 7450'. J	<ol> <li>Ran gyro from packer to in production string. SION.</li> <li>FE HCL. Removed packer.</li> <li>Yested pkr to 1000#. SION.</li> </ol>
work)SEE RULE 1103. 2-2-01: Killed well. Tested equipme 2-3-01: Ran & set Smith Big Bore p surface. Rig down wireline. 3-5-01: Moved in, rigged up. Blew 1-30-01: Ran logs. 5-1-01: Fraced Strawn w/25,170 ga SION. 5-3-01: Pulling out of hole w/3 1/2" 5-4/11-01: Flow testing well. 5-24-01: RIH w/ESP equipment. He 5-25-01: Started ESP. 7-11-01: Production test @ 440 oil, Sundry filed to submit "Actual Well 1 hereby certify that the information above is the signature	ent. RIH with mill to 7775'. SI packer @ 7547', ran Scientific well down. Set test tank & tes ils slick water & 19,000 gals 20 string. RIH w/production strin ooked up to flowline. SION. 12 water and 917 gas. Il Profile'', performed 2-16-01.	ON. Drilling Gyro & smith orie t separator. Prep to flow w % NEFE HCL & 10,000 g og. Displaced annulus. Set C-102 previously submitte e and belief. TITLE Regulatory Agent	entaion survey too ell down/kill & ru gals 20% slick NE packer @ 7450'. T ed w/BHL.Horizon	1. Ran gyro from packer to         in production string. SION.         FE HCL. Removed packer.         Tested pkr to 1000#. SION.         Intal logs submitted 8-20-01.         DATE         10-25-01         A         TELEPHONE NO. 915 686-558
work)SEE RULE 1103. 2-2-01: Killed well. Tested equipme 2-3-01: Ran & set Smith Big Bore p surface. Rig down wireline. 3-5-01: Moved in, rigged up. Blew 4-30-01: Ran logs. 5-1-01: Fraced Strawn w/25,170 ga 5-1-01: Fraced Strawn w/25,170 ga 5-01: Pulling out of hole w/3 1/2" 5-4/11-01: Flow testing well. 5-24-01: RIH w/ESP equipment. He 5-25-01: Started ESP. 7-11-01: Production test @ 440 oil, 5-25-01: Started ESP. 7-25-01: Started ESP. 7-25-01: Started ESP. 7-25-01: Started ESP. 7-25-01: Started ESP. 7-25-01: Started ESP. 7-25-01: S	ent. RIH with mill to 7775'. SI packer @ 7547', ran Scientific well down. Set test tank & tes ils slick water & 19,000 gals 20 string. RJH w/production strin ooked up to flowline. SION. , 12 water and 917 gas. Il Profile", performed 2-16-01.	ON. Drilling Gyro & smith orie t separator. Prep to flow w 0% NEFE HCL & 10,000 g ng. Displaced annulus. Set C-102 previously submitte and belief. TITLE Regulatory Agent 915	entaion survey too ell down/kill & ru gals 20% slick NE packer @ 7450'. T ed w/BHL.Horizon	I. Ran gyro from packer to         In production string. SION.         FE HCL. Removed packer.         Cested pkr to 1000#. SION.         Intal logs submitted 8-20-01.         DATE $10-25-01$