Office					Form C	
District I	Energy	y, Minerals and Na	tural Resources		Revised March 25	, 1999
1625 N. French Dr., Hobbs, NM 8824	10	•		WELL API NO.		
District II		CONSERVATIO	N DIVISION	30-025-34 982		
811 South First, Artesia, NM 88210	OIL			5. Indicate Type of	of Lease	•
District III	10	2040 South Pa		STATE 5		
1000 Rio Brazos Rd., Aztec, NM 874 District IV	10	Santa Fe, NM	87505	6. State Oil & G		
2040 South Pacheco, Santa Fe, NM 8	7505			B1040-1	as Lease 110.	
		EDODTS ON WELL	1.0		Tinit Agraamant	
(DO NOT USE THIS FORM FOR PI DIFFERENT RESERVOIR. USE "A	ROPOSALS TO DRIL	REPORTS ON WELI LL OR TO DEEPEN OR I PERMIT" (FORM C-101)	PLUG BACK TO A	7. Lease Name of Name:	or Unit Agreement	
PROPOSALS.)				Tin Cup "25 State		
1. Type of Well:	. 11 57 .	74l				
Oil Well Gas W	ell X	Other		+		
<ol><li>Name of Operator</li></ol>				8. Well No. 1		
Southwestern Energy Producti	ion Company					
3. Address of Operator				8. Pool name or		
2350 N. Sam Houston Parkwa	v East, Suite 300	- Houston, TX 770	32	Antelope Ridge A	toka Gas	
4. Well Location	· · · · · · · · · · · · · · · · · · ·			·		
4. Well Education						
Unit Letter M	: 660 feet	from the S	line and660	feet from theW	line	
Section 25		Township 2275	Range 34E	NMPM Lea	County	
Section 23	10 Fleva	ation (Show whether	DR, RKB, RT, GR, et			
	3921 GR	ttion (bilow intellier	DN, 111D, 111, ON, C	<i>c.</i> /		
11 01		Dan to Indianta	Matura of Mation	Donort or Other I	Doto	
			Nature of Notice,			
NOTICE O	F INTENTION	NTO:	SUE	SEQUENT REF		_
PERFORM REMEDIAL WORK	K 🔲 PLUG ANI	D ABANDON 🔲	REMEDIAL WOR	rk 🔲	ALTERING CASIN	1G [
TEMPORARILY ABANDON		PLANS 🗆	COMMENCE DE	IILLING OPNS.	PLUG AND	г
I EMPORABILT ADAINDON						
I EMPORABILT ABANDON		_		<del>_</del>	ABANDONMENT	_
	MULTIPLE COMPLET		CASING TEST A	_	ABANDONMENT	L
PULL OR ALTER CASING OTHER:	MULTIPLE COMPLET	FION	CASING TEST A CEMENT JOB OTHER:	ND 🛚		
PULL OR ALTER CASING OTHER:	MULTIPLE COMPLET	FION  S. (Clearly state all p	CASING TEST A CEMENT JOB OTHER: Description of the control of the	ND 🗵	including estimated	C date tion
OTHER:  12. Describe proposed or cor of starting any proposed v	MULTIPLE COMPLET	FION  S. (Clearly state all p	CASING TEST A CEMENT JOB OTHER: Description of the control of the	ND 🗵	including estimated	date
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed or recompilation.  4-2-00 thru 4-7-00	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or cor of starting any proposed vor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 its 9	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5	CASING TEST A CEMENT JOB  OTHER: pertinent details, and e Completions: Attack	give pertinent dates, ich wellbore diagram o	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or corros of starting any proposed was or recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 jts 9 0.25 pps D29. Tail w/ 200 sx	MULTIPLE COMPLET mpleted operation work). SEE RUL	s. (Clearly state all per 1103. For Multiple N-80 & J-55 csg to 5. os D29. Cmt to surf.	CASING TEST A CEMENT JOB OTHER: Detrinent details, and the Completions: Attack (0.039'). Cmt w/ 1560 s Circ 364 sx to reserve	give pertinent dates, ch wellbore diagram of the wellbore diagram of the well bore diagram of the well below the well bore diagram of the well below th	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or corros of starting any proposed was or recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 jts 9 0.25 pps D29. Tail w/ 200 sx	MULTIPLE COMPLET mpleted operation work). SEE RUL	s. (Clearly state all per 1103. For Multiple N-80 & J-55 csg to 5. os D29. Cmt to surf.	CASING TEST A CEMENT JOB OTHER: Detrinent details, and the Completions: Attack (0.039'). Cmt w/ 1560 s Circ 364 sx to reserve	give pertinent dates, ch wellbore diagram of the wellbore diagram of the well bore diagram of the well below the well bore diagram of the well below th	including estimated of proposed comple + 5% D44 + 6% D2	tion
OTHER:  12. Describe proposed or corn of starting any proposed wor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 jts 9 0.25 pps D29. Tail w/ 200 sx	MULTIPLE COMPLET mpleted operation work). SEE RUL	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5 os D29. Cmt to surf.	CASING TEST A CEMENT JOB OTHER: Detrinent details, and the Completions: Attack 0,039'. Cmt w/ 1560 s Circ 364 sx to reserve	give pertinent dates, ch wellbore diagram of the wellb	including estimated of proposed comple + 5% D44 + 6% D2 g to 2000 psi.	20 +
OTHER:  12. Describe proposed or corn of starting any proposed wor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 jts 9 0.25 pps D29. Tail w/ 200 sx  I hereby certify that the inform SIGNATURE	mpleted operation work). SEE RUL!  5/8", 40#, LTC, 11 Class C + 0.25 pp	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5 os D29. Cmt to surf.	CASING TEST A CEMENT JOB OTHER: Detrinent details, and the Completions: Attack (0.039'). Cmt w/ 1560 s Circ 364 sx to reserve	give pertinent dates, ch wellbore diagram of the wellb	including estimated of proposed comple + 5% D44 + 6% D2 g to 2000 psi.	20 +
OTHER:  12. Describe proposed or corn of starting any proposed wor recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 jts 9 0.25 pps D29. Tail w/ 200 sx  I hereby certify that the information of the starting and the information of the starting and the	mpleted operation work). SEE RUL!  5/8", 40#, LTC, 11 Class C + 0.25 pp	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5 os D29. Cmt to surf.	CASING TEST A CEMENT JOB OTHER: Detrinent details, and the Completions: Attack 0,039'. Cmt w/ 1560 s Circ 364 sx to reserve	give pertinent dates, ch wellbore diagram of the wellb	including estimated of proposed comple + 5% D44 + 6% D2 g to 2000 psi.	20 +
OTHER:  12. Describe proposed or cor of starting any proposed or recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 jts 9 0.25 pps D29. Tail w/ 200 sx  I hereby certify that the information of the starting any proposed or correctly starting and starting	mpleted operation work). SEE RUL!  5/8", 40#, LTC, 11 Class C + 0.25 pp	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5 os D29. Cmt to surf.	CASING TEST A CEMENT JOB OTHER: Detrinent details, and the Completions: Attack 0,039'. Cmt w/ 1560 s Circ 364 sx to reserve	give pertinent dates, ch wellbore diagram of the wellb	including estimated of proposed comple + 5% D44 + 6% D2 g to 2000 psi.	20 +
OTHER:  12. Describe proposed or cor of starting any proposed or recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 jts 9 0.25 pps D29. Tail w/ 200 sx  I hereby certify that the information of the starting any proposed or recompilation.	mpleted operation work). SEE RUL!  5/8", 40#, LTC, 11 Class C + 0.25 pp	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5 os D29. Cmt to surf.	CASING TEST A CEMENT JOB OTHER: Detrinent details, and the Completions: Attack 0,039'. Cmt w/ 1560 s Circ 364 sx to reserve	give pertinent dates, ch wellbore diagram of the wellb	including estimated of proposed comple + 5% D44 + 6% D2 g to 2000 psi.	3/00
OTHER:  12. Describe proposed or cor of starting any proposed or recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 jts 9 0.25 pps D29. Tail w/ 200 sx  I hereby certify that the inform SIGNATURE  Type or print name Cathy/Ro (This space for State use)	mpleted operation work). SEE RUL!  5/8", 40#, LTC, 11 Class C + 0.25 pp	S. (Clearly state all p E 1103. For Multiple N-80 & J-55 csg to 5 os D29. Cmt to surf.	CASING TEST A CEMENT JOB  OTHER:  Detrinent details, and the Completions: Attack  3,039'. Cmt w/ 1560 strict 364 sx to reserve the best of my knowledge.  Drilling Technicia	give pertinent dates, ch wellbore diagram of the wellb	including estimated of proposed comple + 5% D44 + 6% D2 g to 2000 psi.	tion
OTHER:  12. Describe proposed or cor of starting any proposed or recompilation.  4-2-00 thru 4-7-00  Drill to 5,039'. Run 112 jts 9 0.25 pps D29. Tail w/ 200 sx  I hereby certify that the information of the starting any proposed or recompilation.	mpleted operation work). SEE RUL!  5/8", 40#, LTC, No Class C + 0.25 presented to the company of	S. (Clearly state all pt E 1103. For Multiple N-80 & J-55 csg to 5 os D29. Cmt to surf.	CASING TEST A CEMENT JOB  OTHER:  Detrinent details, and the Completions: Attack  3,039'. Cmt w/ 1560 strict 364 sx to reserve the best of my knowledge.  Drilling Technicia	give pertinent dates, ch wellbore diagram of the wellb	including estimated of proposed comple + 5% D44 + 6% D2 g to 2000 psi.	3/00