Form 3160-5 (June 1990) UNITED STATES DEPARTMENT OF THE INTERIOR N. French Dr. BUREAU OF LAND MANAGE HODDS, NM 88240 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Seriai No. NM 0557686 6. If Indian, Allotee or Tribe Name
Use "A	7. If Unit or CA, Agreement Designation		
	7. II Olit of CA, Agroenon Designation		
1. Type of Well			1
	8. Well Name and No.		
2. Name of Operator	SEMU, Well #165		
CONOC	9. API Well No.		
3. Address and Telephone No.	30 025 35835		
10 DESTA DR. STE. 1	10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec.	Cass Penn		
1	11. County or Parish, State		
			Lea County, NM
CHECK APPR	OPRIATE BOX(s) TO INDIC	ATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTIO			
Notice of Intent		Abandonment Recompletion	Change of Plans New Construction
Subsequent Repo	n	Plugging Back	Non-Routine Fracturing
Final Abandonmo		Casing Repair Altering Casing Other TD, long string, release rig	Water Shut-Off Conversion to Injection Dispose Water Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed C	Operations (Clearly state all pertinent details, an	d give pertinent dates, including estimated date of starting	g any proposed work. If well is directionally drilled

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-13-02: Reached total depth of 8200'. Circulate and condition hole for logs.

3-14-02: Ran GR/CNL/Cal log from TD to surface. Cut sidewall cores.

2 2

5

3-15-02: Ran 5 1/2", 17#, P110/L80, LT &C to 8199'. Cemented with 1st stage: pumped 36 bbls mud clean 1, 3 bbls H20, 32 bbls MAGNE Plus cement + 1% sodium Borate, displace w/15bbls H20 & 173 bbls brine. Bump plug w/750 psi. Open DV tool w/1830 psi. Circulate cement off tool. WOC. Circulate w/rig. 2nd Stage: pumped 10 bbls H20, 49 bbls lead (50:50:10) C + 5% salt + 1/4#sx CF + 5# LCM-1 + 2/10% CD-32. 120 bbls tail (61:15:11) C + 5% salt + 1% FL-62 + 5# LCM-1. Displaced with 75 bbls H20 + 103 brine. Bump plug e/2800 psi. Open 2nd DV tool w/1860 psi. Circulated cement off DV tool w/rig. Circulate 205 sx to pit. WOC. Circulate w/rig. 3rd Stage: pumped 10 bbls H20, 397 bbls lead Cl C (50:50:10) + 5% salt + 1/4# CF + 5# LCM-1, 48 bbls tail, C + 2% CaCl2. Displaced w/116 bbls H20. Bumped plug w/3080 psi. Circulated l05 sx to pit. Released rig.

$\overline{\Lambda}$	
14. 1 hereby certify that the foregoing is your and correct. Ann E. Ritchie Signed Addition The Conference of the Regulatory Agent	Date 4-5-02
(This space for Federal or State office use) Approved by ORIG, SGD.) DAVID R. GLASS Conditions of approval APR 1 5 2002	Date
BLM(6) Title 18 U.S.C. Section 1001 makes it a cirme for any person knowingly and willfully to make to any department or or representations as to any matter within its juncticition. PETRO FULL Figure 10 - 10 - 10 - 10 - 10 - 10 - 10 - 10	

BORNET STREET HECENLED