

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

WARRANTS OFFICE O. G. C.

MAR 24 11 49 AM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.		

B-6807

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
3. Address of Operator	9. Well Name
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>N</u> 990 FEET FROM THE <u>S</u> LINE AND <u>2310</u> FEET FROM THE <u>W</u> LINE, SECTION <u>13</u> TOWNSHIP <u>21 S</u> RANGE <u>34 E</u> NMPM.	11. <u>Wilson</u>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
<u>3673 DF</u>	<u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The subject well was drilled to TD 4206' PB 3510' with 7" casing at 3643' cemented with 500 SX

Well was shut in Temporarily abandon 3-24-61

Permission is requested to plug and abandon subject well as follows:

15 SX cement plug 3400' - 3510'  
20 SX cement plug in 7" - Top cement by Temp survey 1650'  
20 SX cement plug at top salt. 1747' (Unless 7" is shot off at or above this point)  
25 SX cement plug across surface casing 225'  
10 SX cement plug at surface with regulation marker  
8½ - 9# Native mud between cement plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Roger L. Law TITLE Vice President DATE 3-11-66

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: