




AREA 640 ACRES
LOCATE WELL CORRECTLY

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

WELL RECORD

Mail to Oil Conservation Commission, Santa Fe, New Mexico, or its proper agent not more than twenty days after completion of well. Follow instructions in the Rules and Regulations of the Commission. Indicate questionable data by following it with (?). SUBMIT IN TRIPPLICATE. FORM C-110 WILL NOT BE APPROVED UNTIL FORM C-105 IS PROPERLY FILLED OUT.

Wilson Oil Company **Santa Fe, New Mexico**
Company or Operator Address
State B-9084 Well No. **39** in **NW NW** of Sec. **15**, T. **21**
Lease
R. **34**, N. M. P. M., **West Wilson** Field, **Lea** County.
Well is **330** feet south of the North line and **4950** feet west of the East line of **Sec 15**.
If State land the oil and gas lease is No. **B. 9084** Assignment No. _____
If patented land the owner is _____, Address _____
If Government land the permittee is _____, Address _____
The Lessee is **Wilson Oil Company**, Address **Santa Fe, N.M.**
Drilling commenced **1-26-50** 19____ Drilling was completed **3-10-50** 19____
Name of drilling contractor **Cleaver Drilling Co.**, Address **Alamogordo N.M.**
Elevation above sea level at top of casing **3716** feet.
The information given is to be kept confidential until _____ 19____

OIL SANDS OR ZONES

No. 1, from _____ to _____ No. 4, from _____ to _____
No. 2, from _____ to _____ No. 5, from _____ to _____
No. 3, from _____ to _____ No. 6, from _____ to _____

IMPORTANT WATER SANDS

Include data on rate of water inflow and elevation to which water rose in hole.
No. 1, from **385** to **390** feet.
No. 2, from **582** to **588** feet.
No. 3, from **1070** to **1080** feet.
No. 4, from **3980** to **4058** feet.

CASING RECORD

SIZE	WEIGHT PER FOOT	THREADS PER INCH	MAKE	AMOUNT	KIND OF SHOE	CUT & FILLED FROM	PERFORATED		PURPOSE
13	48	8rd	new	152					Surface Water shut-off
10	38	"	S.H.	822					
8	28	"	"	1385					

MUDDING AND CEMENTING RECORD

SIZE OF HOLE	SIZE OF CASING	WHERE SET	NO. SACKS OF CEMENT	METHODS USED	MUD GRAVITY	AMOUNT OF MUD USED
15	13	172	150	Haliburton		

PLUGS AND ADAPTERS

Heaving plug—Material _____ Length _____ Depth Set _____
Adapters — Material _____ Size _____

RECORD OF SHOOTING OR CHEMICAL TREATMENT

SIZE	SHELL USED	EXPLOSIVE OR CHEMICAL USED	QUANTITY	DATE	DEPTH SHOT OR TREATED	DEPTH CLEANED OUT

Results of shooting or chemical treatment _____

RECORD OF DRILL-STEM AND SPECIAL TESTS

If drill-stem or other special tests or deviation surveys were made, submit report on separate sheet and attach hereto.

TOOLS USED

Rotary tools were used from _____ feet to _____ feet, and from _____ feet to _____ feet
Cable tools were used from **0** feet to **4058** feet, and from _____ feet to _____ feet

PRODUCTION

Put to producing _____, 19____
The production of the first 24 hours was _____ barrels of fluid of which _____% was oil; _____% emulsion; _____% water; and _____% sediment. Gravity, Be _____
If gas well, cu. ft. per 24 hours _____ Gallons gasoline per 1,000 cu. ft. of gas _____
Rock pressure, lbs. per sq. in. _____

EMPLOYEES

J. B. Craig, Driller **W. E. Mashburn**, Driller
R. R. Williams, Driller **J. S. Taylor**, Driller

FORMATION RECORD ON OTHER SIDE

I hereby swear or affirm that the information given herewith is a complete and correct record of the well and all work done on it so far as can be determined from available records.

Subscribed and sworn to before me this **10** day of **March**, 19 **50**

Notary Public
My Commission expires **August 28 1953**
Artesia, New Mex. **3-10-50**
Place Date
Name **Laurel Lamb**
Position **Assistant to the President**
Representing **Wilson Oil Company**
Company or Operator
Address **Artesia, New Mexico**

FORMATION RECORD

FROM	TO	THICKNESS IN FEET	FORMATION
0	15	15	Caliche
15	130	115	Sand
130	910	780	Red sand and shale
910	1090	180	Red shale and water sand
1090	1760	670	Red shale
1760	1915	155	Anhydrite and red shale
1915	2130	215	Salt and anhydrite
2130	3040	910	Salt and potash with stringers of anhy.
3040	3090	50	Anhydrite and blue shale
3090	3260	170	Salt and potash
3260	3325	65	Anhydrite
3325	3470	145	Salt
3470	3510	40	Anhydrite with stringer salt
3510	3540	30	Anhydrite and lime
3540	3722	182	Lime Brown and gray.
3722	3765	43	Broken sand and lime
3765	3790	25	Broken lime
3790	3850	60	Red sand Show salt water @ 3800-10
3850	3982	132	Lime
3982	3992	10	Lime Small amount sulfur water
3992	4058	66	Lime with stringers showing sulfur water
4058' Total Depth			
Plugged and Abandon.			