

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O.C.C.  
NEW MEX CO OIL CONSERVATION COMMISSION  
MAR 24 11 48 AM '66

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. State Oil & Gas Lease No.
2. Name of Operator <b>Wilson Oil Company</b>		7. Unit Agreement Name
3. Address of Operator <b>P. O. Box 457, Artesia, New Mexico</b>		8. Farm or Lease Name <b>State</b>
4. Location of Well UNIT LETTER <b>L</b> <b>1980</b> FEET FROM THE <b>S</b> LINE AND <b>990</b> FEET FROM THE <b>N</b> LINE, SECTION <b>23</b> TOWNSHIP <b>21 S</b> RANGE <b>24 E</b> NMPM.		9. Well No. <b>34</b>
10. Field and Pool, or Wildcat		11. County <b>Lea</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>1708 DF</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The subject well was drilled to 13922' to 13985' with 7" casing 13971' cemented with 500'.

The well was shut in April 1965

Permission is requested to plug and abandon the well as follows:

- 15' of cement plug 13780' - 13805'
- 20' of cement plug at top 7" top cement by temperature survey 1390'
- 20' of cement plug at top salt at 13110' (Unless 7" is shot off at or above this point)
- 25' of cement plug across surface casing 1315'
- 10' of cement plug at surface with regulation marker
- 3' - 9' native mud between cement plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>[Signature]</u>	TITLE <u>Vice President</u>	DATE <u>4-1-66</u>
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		