

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

APR 19 12 42 PM '66

Form C-102
Supersedes Old
C-102 and C-103
Effective 1-1-65

30-025-02584

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
State B - 10867

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator	8. Firm or Lease Name
Morris R. Antweil	State 2
3. Address of Operator	9. Well No.
P. O. Box 2010	5
4. Location of Well	10. Field and Pool, or Wildcat
Interval 270 FEET FROM THE South LINE AND 1559 FEET FROM	Wilson
LINE, SECTION 24 TOWNSHIP 21 RANGE 34 NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
DF 3318	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
DRILL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

17. Description of Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spotted 35 sx to cover perforation.
2. Loaded hole with mud laden fluid.
3. Spotted 25 sx at stub at 1600'.
4. Spotted 25 sx at bottom of surface shoe.
5. Spotted 10 sx plug at top of surface. and set marker.

- * Top of salt at 1600'
- ** Base of salt at 3700' - covered by casing.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Hobbs Pipe & Supply Co.

SIGNED *D. D. Hobbs*

TITLE _____

DATE **4/18/66**

APPROVED BY *John W. Runyan*

TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: