

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
REGISTRATION OFFICE	
OPERATOR	

(Form C-102)  
(Revised 7/1/52)

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	<b>X</b>	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

Hobbs, New Mexico  
(Place)

June 30, 1964  
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the **Pan American Petroleum Corporation**

(Company or Operator) **State "NM"** Well No. **5** in **F** (Unit)  
**SE** **NW** **24** **21-S** **34-E** **Wilson**  
(40-acre Subdivision)  $\frac{1}{4}$  of Sec. **24**, T. **21-S**, R. **34-E**, NMPM, Pool  
**Lea** County.

TD 3900'

FULL DETAILS OF PROPOSED PLAN OF WORK  
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

It is proposed to plug and abandon this depleted well as follows:

Spot cement plugs & etc.

1. 35 sx across perforations 3788-94' (bridge plug at 3875')
2. Located free point, cut & pull 7" casing
3. 25 sx half in and out of 7" stub
4. locate free point, cut and pull 8-5/8" casing
5. 25 sx cement half in and out of 8-5/8" stub
6. 25 sx cement in and out of surface casing shoe at 142'
7. 10 sx cement at surface and erect PXA marker
8. Make final cleanup and restore ground to contour.

Approved....., 19.....  
Except as follows:

Approved  
OIL CONSERVATION COMMISSION

By.....  
Title.....

**Pan American Petroleum Corporation**  
Company or Operator

By.....

Position **Area Superintendent**  
Send Communications regarding well to:

Name **V. E. Staley**  
Address **Box 68 - Hobbs, New Mexico - 88240**