

APPROVED **ILLEGIBLE**

Form 9-231a  
(Feb. 1961)

FEB 3 1962

(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-2388.4  
Approval expires 12-31-60.

Land Office **New Mexico**

Lease No. **N.M. 01162**

Unit

E. W. STANDLEY  
DISTRICT ENGINEER

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

*Inspected 1-30-62  
O.K. for Abandonment J.S.*

FEB 3 1962

**SUNDRY NOTICES AND REPORTS ON WELLS**  
HOBBS, NEW MEXICO

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT <b>X</b>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 4, 1962

**FEDERAL**

Well No. **1** is located **660** ft. from **[S]** line and **660** ft. from **[E]** line of sec. **11**  
**SE 11** **21-S** **36-E** **NMPM**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Wildcat** **Lea** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **3868** ft.

**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**TD 3671** **8 5/8 Surface Pipe @ 1622 Cement Circulation**

Plugged and abandon well in the following manner, 296 sacks 50-50 pozmix with 8% gel. Solid plug from TD to 1271 and 10 sack plug in surface. Surface marker is now installed and the location has been cleaned and ready for inspection. Copy of Affidavit from Halliburton is attached.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Gackle Drilling Company, Inc.**

Address **P. O. Box 2076**

**Hobbs, New Mexico**

By *[Signature]*

Geologist