## NEW MEXICO STATE LAND OF SANTA FE, NEW MEXICO DEPARTMENT OF THE STATE GEOLOGIST SANTA FE

## NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Wink,	Texas	XXXX 6/22	, 3 <b>3</b>
Mr. J. D. Hunter, Carlsbad. Santa Fe, New Mexico.	,	21, 12011,	19
Santa Fe, New Mexico.  Dear Sir:			
You are hereby notified that it is our intenti	ion to abandon State	ц <b>В</b> п	Well
No. 3 in NR of SEc	Z Twp. 21-S	, Rge. <b>33-R</b>	
N. M. P. M., Lea	Oil Field, Lea		County.
We plan to commence work on 4-28-33		, 19	
The reasons for wishing to abandon the well ater enroachment in oil hori	are as follows:		
The present condition of the well is as follows 3778-3974 Lead Cluz, 3774-376	s: 5 Cem <b>ent,</b> Madde <b>d</b>	to top.	
The work which we propose to do in abar Plug solifd with rock, steel bail dry, mud to 3722, bridge dusp 10 sacks cement, pull 84 and steel cuttings and dusp 10 335, bridge and dump 10 sx censx. cement, fill with mud to	cutting to3740, d with reck and st "Casing, mud to 0 sx cement. Full ment, mud & 120' top and cement c	use cement to 3 sel cutting and 1783, bridge wa 10" Casing, mu	th roc
	Sincerely yours,		
Approved 5-23 1933	Cranfill-Re	ynolds Company	
Except as follows:	By Month fin	Company or O	perator.
•	Position	rintendent	****************
	Send communications i	-	***************************************
1031 1	Name G. C. Grif		
State Geologist or Oil and Gas Inspector.	Address P. O. Box		