

STATE OF NEW MEXICO
NATURAL RESOURCES DEPARTMENT
OIL CONSERVATION DIVISION
P. O. BOX 7008
SANTA FE, NEW MEXICO 87501

OIL CONSERVATION DIVISION
P. O. BOX 7008
SANTA FE, NEW MEXICO 87501

Form O-10
Revised 10-79

10. Indicate Type of Lease
State ☒ For ☐
11. State Oil & Gas Lease No.
E-8241

SUNDARY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PRODUCTION REPORTS OR TO REPORT ON PLUG BACKS OR A DIFFERENT RESERVING.
ALL INFORMATION FOR PRODUCTION REPORTS SHOULD BE REPORTED ON THE PRODUCTION REPORT.

12. Unit Agreement Name
B
13. Name of Lessee
Ernie L. Hegwer

14. Well No.
No. 2

15. Field and Pool, or Wildcat
Eumont

16. Elevation (Show Location of, RT, GR, etc.)
3593 G.L.

17. County
Tea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

18. Altering casing
19. Plug and abandonment
20. Change plans
21. Other

22. Remedial work
23. Commence drilling down
24. Casing test and cement job
25. Other

26. Altering casing
27. Plug and abandonment
28. Other

Describe Progress or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Friday, June 29 - Rig up Ralph Johnson. Run in hole with 6 1/4" skirted bit & scraper. Tag fill at 3892'. Trip out of hole. Shut well in.

Saturday June 30 - Schlumberger rig up & perforate at following intervals 2 shots per ft. 3770, 3780, 3790, 3794, 3810, 3820, total of 12 shots. 3862 through 3878 2 shots per ft. through-out, total of 32 shots.

Acidize 3862-3878 with 4,000 gals. 15% NE,FE, acid w/5 gals clay stabilizer, isolate 3770 to 3820 with Bridge plug & Packer, acidize with 1,000 gals. 15% NE, FE acid, retrieve Bridge Plug and packer, trip out of hole. Shut well in.

Sund. July 1 - Swab well down, run rods and pump. Pressure tubing to 500#.

Tues. July 2 - Check well, no pressure build-up. Hang well on, place on production, recovering load. Release rig.

194 total load to recover.

Fri. - 30 Bbls. load water

Sat. - 30 Bbls. load water

Sun. - 20 Bbls. load water

Mon. - 20 Bbls. load water

Tues. - 20 Bbls. 3 1/2 oil, blow of gas

Wed. - 20 Bbls. 3 1/2 oil, blow of gas.

Well currently pumping 24 Hrs. per day.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signature _____ TITLE Owner DATE July 7, 1981

Signature _____ TITLE _____ DATE _____

Signature _____ TITLE _____ DATE _____

RECEIVED

JUL 13 1981

OIL CONSERVATION DIV