

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBBS OFFICE O. C. C. Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

NEW MEXICO OIL CONSERVATION COMMISSION

MAR 24 11 50 AM '66

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-1399

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Temporarily Abandoned	7. Unit Agreement Name
2. Name of Operator Wilson Oil Company	8. Farm or Lease Name Shell State
3. Address of Operator P. O. Box 457, Artesia, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER N 4620 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 7 TOWNSHIP 21 RANGE 35 NMPM.	10. Field and Pool, or Wildcat Wilson
15. Elevation (Show whether DF, RT, GR, etc.) 3684 DF	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The subject well was drilled to F.D. 3902' with 7" casing set at 3636' with 100 SX and 5 1/2" liner 3421' to 3901' with 150 SX.

The well was temporarily abandon in October, 1956

Permission is requested to plug and abandon the well as follows.

15 SX cement plug 3750 - 3879'
 20 SX " " at top 7"
 20 SX " " at top salt 1805' (unless 7" is shot off at or above this point)
 25 SX " " across surface casing 106'
 10 SX " " surface of regulation marker
 8 1/2 - 9" Native mud between cement plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Vice President DATE December 1, 1965

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: