STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	T		
DISTRIBUTION			
SANTA FE			
FILE			
U.S.G.S.			
LAND OFFICE	1		
DPERATOR	7		

UIL CONSERVATION DIVISION

	OIL CONSERVA	THOM DIVISION	
DISTRIBUTION			Form C-103 -
SANTA FE	SANTA FE, NEW MEXICO 87501		Revised 10-1-78
FILE	1	W. 27(100 0750)	
U.S.G.S.			5a, Indicate Type of Lease
LAND OFFICE			State Fee
DPERATOR			5. State Cil & Gas Lease No.
h			S, since Chr & Gas Brose No.
SUNDRY	Y NOTICES AND REPORTS ON POSALS TO DAIL OR TO DEEPEN ON PLUG BON FOR PERMIT -" (FORM C-101) FOR SUC	WELLS	
(DO NOT USE THIS FORM FOR PACE	CSALS TO DATLE ON TO DEEPEN OR PLUG &	ACK TO A DIFFERENT RESERVOIR.	
1.	ON FOR PERMIT 2" (FORM C-101) FOR SUC	H PROPOSALS.)	
/			7. Unit Agreement Name
WELL X	OTHER.		j
2. Name of Operator			B, Farm or Lease Name
1700			b am or Lease Name
ARCO Oil and Gas Company - Div of Atlantic Richfield Company			Endura DE State
3. Address of Operator			9. Well No.
P O Box 1710 Hobbs	Nor- Manda - 000/0		1 ,
P. O. Box 1710, Hobbs,	New Mexico 88240		4
			10. Field and Pool, or Wildcat
LANT LETTER I 19	80 FEET FROM THE South	660	Eumont Oil
1	THE THOM THE BOART	LINE AND OUD FEET PRO	mmmmmmm"
Fact	10		
THE EAST LINE, SECTION	N 12 TOWNSHIP 21S	HANGE 35E NMPN	
			VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
		,,,	, Y/////////
777777777777777777777777777777777777777	3591' GL		Lea
Check A	appropriate Box To Indicate N	latura of Nation Paper on O	des Dese
		ature of Notice, Report of Ot	ner Data
NOTICE OF IN	TENTION TO:	SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
Ħ			ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABAHDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		ATHER Return Eumont (Queen Oil to Production [X]
		Tree dell Bonone	deen off to Froduction X
OTHER			
17. 5		<u></u>	
work) SEE RULE 1103.	stations (Clearly state all pertinent deta	nils, and give pertinent dates, includin	g estimated date of starting any proposed
Epiny SEE WOLL 1150.			
Returned well to Eumont	Oil production in the f	017 0004 000	
Ended well to Edmone	off production in the 1	offowing manner:	
1. Installed pumping un	it.		
2. MIRU 8/05/87. RTH w	/rods and pump. Set pum	n at 3701! Dim and 0 a	7001
3 Fumant Ouser Odd	rods and pamp, set pum	pat 3/01. PKr set @ 3	3780'.
5. Editoric Queen Off prod	ducing through perfs 379	0-3835' and 3855-3908' P	BD. Final Report.
			• •
		•	
		•	
·			
	•		
		,	
is. I hereby certify that the information a	house to the same and asset to the same as		
10, I hereby certify that the information a	ouve is true and complete to the best of	i my knowledge and belief.	
1	• . /		
Aleman	.T.	Area Prod Cont	0/10/07
SIGHED / WOUND STY	TITLE I	Area Prod. Supt.	_ DATE8/10/87

AUG 1 7 1987

APPROVED BY DISTRICT ! SUPERVISOR

ORIGINAL SIGNED BY JERRY SEXTON