WEW A LICO OIL CONSERVATION COMM. JON

Santa Fe, New Mexico

MISCELLANEOUS NOTICES



Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indic					
NOTICE OF INTENTION TO TEST CAS SHUT-OFF	SING X		NTENTION TO ST LLY TREAT WE		
NOTICE OF INTENTION TO CHANGE I	PLANS	NOTICE OF IN OTHERWI	TENTION TO PU SE ALTER CASI	LL OR NG	
NOTICE OF INTENTION TO REPAIR V	WELL	NOTICE OF I	NTENTION TO PI	UG WELL	
NOTICE OF INTENTION TO DEEPEN W	ELL				
<u> Anna de la composition della composition de la composition della composition della composition della composition della composition della composition della</u>	Hobbs	New Mexico		April 14,	1945
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico.		Tiace		Date	
Gentlemen:					
Following is a notice of intention to do cer Stanolind Oil & Gas Co.	State				/4 of N
Company or Operator of Sec. 19 T. 21-8 I	Lease				
Taa	County.	,			,
יישר וווים	ATT S OF PR	OPOSED PLAN	TAUM TO I		
		V			
FOLLOW INSTRUCTIONS	IN THE RULE	S AND REGULAT	IONS OF THE CO	MMISSION	
			_		
On April 13, 1945 at 6:00 P	M, 48 hours			etting 370	5 feet
		will have el	apsed since a		
7" OD 20# New Seamless casin	g as oil st	will have elering and come	apsed since a		
	g as oil st	will have elering and come	apsed since a		
7" OD 20# New Seamless casin	g as oil st	will have elering and come	apsed since a		
7" OD 20# New Seamless casin casing shut-off will be test	g as oil st	s will have elering and come ows:	apsed since s ated with 75	sacks, At	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off	g as oil st ed as folk d after dri	s will have elering and come ows:	apsed since a mied with 75 plug; if bot	sacks. At h tests in	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off resumed.	g as oil st ed as folk d after dri	s will have elering and come ows: illing coment obtained, dril	apsed since a nted with 75 plug; if bet ling operatio	sacks. At h tests income will be	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off resumed.	g as oil st ed as folk d after dri	s will have elering and come ows: illing coment obtained, dril	apsed since anted with 75 plug; if betling operatio	sacks. At h tests in ns will be	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off resumed. APR 17 1945	g as oil sted as follo	s will have elering and come ows: illing coment obtained, dril	apsed since a nted with 75 plug; if bet ling operatio	sacks. At h tests in ns will be	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off resumed. APR 17 1945	g as oil sted as follo	s will have elering and come ows: illing coment obtained, dril	apsed since anted with 75 plug; if betling operatio	sacks. At h tests in ns will be	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off resumed. APR 17 1945	g as oil sted as follo	s will have elering and come ows: illing coment obtained, dril	apsed since anted with 75 plug; if betling operatio	h tests income as will be	this t
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off resumed. APR 17 1945	g as oil sted as follo	Stand By Aug. Position Fi	apsed since and the desired with 75 plug; if bet ling operation Company or op	sacks. At h tests inc ns will be grader andent	this to
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off resumed. ApprovedAPR 17 1945	g as oil sted as follo	Stand By Position Position Send	apsed since a nice with 75 plug; if bet ling operation company or operat	h tests income solution in the state of the	this to
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off resumed. ApprovedAPR 17 1945 except as follows:	g as oil sted as follo	Stand Stand By Position Fi Send Name Mr.	apsed since a nice with 75 plug; if bet ling operation of the company or operation of the communications recommunications rec	h tests income service and the	this to
7" OD 20# New Seamless casin casing shut-off will be test Bail hole dry before an a satsifactory shut-off resumed. ApprovedAPR 17 1945 except as follows:	g as oil sted as follo	Stand Stand By Position Fi Send Name Mr.	plug; if bet ling operation Company or Op Communications re Ralph L. Hend	h tests income service and the	this to

en de la companya de la co

TO THE SECOND SERVICE OF THE SECOND S

en de la companya de la co

en de la composition La composition de la

Light State $(-\mathbf{x}^{(k+1)})_{k=0} = (-\mathbf{x}^{(k+1)})_{k=0} + (-\mathbf{x}^{(k+1)})_{k=0} + (-\mathbf{x}^{(k+1)})_{k=0}$