NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WEELS THE PART

Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	ritalesse int	ure or repo	rt by checking belo	w.	
EPORT ON BEGINNING DRILLI OPERATIONS	NG		REPORT ON I	REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		Х	REPORT ON PULLING OR OTHERWISE ALTERING CASING		SE
EPORT ON RESULT OF TEST OF SHUT-OFF	F CASING		REPORT ON I	EEPENING WELL	
EPORT ON RESULT OF PLUGGI	NG OF WELL				
	May 23	, 1955		Dallas, Texas	
			Date	Pl	ace
ollowing is a report on the work do					
right & Schiff	Supe	rior-Sta	te	Well No	in the
right & Schiff Company or Open E 1/4 cf SW 1/4	of Sec	25	, T. 21-S	, R 35– E	, N. M. P. M.,
ndesignated					
	DAT PLAST	enc with			mr her gar
ell would not back flow. t a rate of 6 bbls. oil p paded well w/oil and ran etween the two zones. So one flowing thru the tub	Swabbed a per hour. Guiberson wabbed well ing. Upper	nd flower Recovere hook wal down.	ed circulating ed all but 50 cl packer back Set packer is nut-in w/550 p.	oil, flush oil arbbls. of circulation well. Swing polating the two so	nd treating ing oil. backer at 30 bnes. Lower
roke formation with 1900 all would not back flow. It a rate of 6 bbls. oil poaded well w/oil and ran etween the two zones. Stone flowing thru the tube oper zone thru casing and vitnessed by Joe C. Gourlay	Swabbed a per hour. Guiberson wabbed well ing. Upper	nd flower Recovere hook wal down.	ed circulating ed all but 50 cl packer back Set packer is aut—in w/550 packer. Schiff Company	oil, flush oil arbbls. of circulation well. Swing polating the two zonsi well head pressured by the control of	per minute. Ind treating ing oil. Dacker at 3: Dones. Lower at 5: Sure. To t
ell would not back flow. Is a rate of 6 bbls. oil produced well would and ran between the two zones. Some flowing thru the tube oper zone thru casing and witnessed by Jos C. Gourlay	Swabbed a per hour. Guiberson wabbed well ing. Upper nulus at a	nd flower Recovere hook wal down. zone sh later da	d circulating d all but 50 all packer back Set packer is nut-in w/550 pate. Schiff Company I hereby swear or is true and correct. Name Produ	oil, flush oil arbbls. of circulation well. Swing polating the two zers well head pressure affirm that the information of the state of	per minute. Ind treating ing oil. Dacker at 3: Dones. Lower sure. To to
ell would not back flow. t a rate of 6 bbls. oil paded well w/oil and ran etween the two zones. So one flowing thru the tube oper zone thru casing and vitnessed by Joe C. Gourlay NAPPROVED:	Swabbed aper hour. Guiberson wabbed welling. Upper nulus at a	nd flower Recovere hook wall down. zone sh later da Bright	ed circulating ed all but 50 el packer back Set packer is eut-in w/550 per externation Schiff Company I hereby swear or	oil, flush oil arbbls. of circulation well. Swing polating the two zers well head pressured by the control of t	oer minute. In treating ing oil. Dacker at 3: Dacker at

Dallas, Texas