

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1671	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name Atlantic State
3. Address of Operator P.O. Box 1710 - Hobbs, New Mexico 88240		9. Well No. 3
4. Location of Well UNIT LETTER <u>I</u> <u>330</u> FEET FROM THE <u>East</u> LINE AND <u>2310</u> FEET FROM THE <u>South</u> LINE, SECTION <u>25</u> TOWNSHIP <u>21S</u> RANGE <u>35E</u> NMPM.		10. Field and Pool, or Wildcat Eumont Yates Seven Rivers
15. Elevation (Show whether DF, RT, GR, etc.) 3630' DF		12. County Lea

## 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Shut-in</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well is shut-in and date shut-in is unknown. The well was shut-in because it was uneconomical to produce in the present zone. Plans are to stimulate present zone during the 1st qtr 1976.

*Expires 10/1/76*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>AV Richs</u>	TITLE <u>Dist. Prod. &amp; Drlg Supt.</u>	DATE <u>9-26-75</u>
Only Signed by John R. Ryan Geologist		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		