

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin a copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by a different plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature of Notice by Checking	Below	
Notice of Intention to Change Plans		Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	x	Notice of Intention to Plug Back	Notice of Intention to Set Liner	
Notice of Intention to Squeeze		Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate		Notice of Intention (Other)	Notice of Intention (Other)	
OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO Artesia, 1		Artesia, New Mexico	June 7, 1953 (Date)	
Gentlemen:		· · · · · · · · · · · · · · · · · · ·	Atlantic-State	
Following is a Notice of Intention to do certain work as describe		mpany	Well Noin	I (Unit)
NF: 1/ SF 1/ -	pany or Operato	г) , т 21 , r 35 ,nmi	PM Eunice	Po
Well drille	(FOLLO)	LL DETAILS OF PROPOSED PLAN VINSTRUCTIONS IN THE RULES AN Otal depth 3941 . No co	ommercial oil or gas	shows.
Propose to to surface. cement plug 3600' - whi 1600' - whi	(FOLLOW) ed to to plug ar Proposes be put to is of	V INSTRUCTIONS IN THE RULES AN	mmercial oil or gas ng set at 210' and of of rotary mud and to at the following place and below base of se 10'. Each plug will	set set: lt, consist
Propose to to surface. cement plug 3600' - whi 1600' - whi of 15 sacks	(FOLLOW) ed to to plug ar Propose s be pu ich is o ich is o ich is o	otal depth 3941. No cond abandon. 8 5/8" casions to leave hole full comping down drill pipe at the control of possible pays on top of salt and at 21	mmercial oil or gas ng set at 210' and of of rotary mud and to at the following place and below base of se 10'. Each plug will	set set: lt, consist
Propose to to surface. cement plug 3600' - whi 1600' - whi	(FOLLOW) ed to to plug ar Propose s be pu ich is o ich is o ich is o	otal depth 3941. No cond abandon. 8 5/8" casions to leave hole full oumping down drill pipe at on top of possible pays on top of salt and at 21 arker will be set in con	mmercial oil or gas ing set at 210' and of if rotary mud and to at the following place and below base of se in Each plug will icrete at the surface	set set: lt, consist
Propose to to surface. cement plug 3600' - whi 1600' - whi of 15 sacks	(FOLLOW) ed to to plug ar and proposed to to to plug ar and proposed to to to plug ar and proposed to	otal depth 3941. No cond abandon. 8 5/8" casi ose to leave hole full omping down drill pipe a on top of possible pays on top of salt and at 21 arker will be set in consider. By	mmercial oil or gas ng set at 210' and of of rotary mud and to at the following place and below base of se 10'. Each plug will	emented set ses: alt, consist