

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
B-158	

SUNDARY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR REEVALUATE OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL FORM C-101 FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator Texaco Inc.	8. Farm or Lease Name NCT-5 New Mexico 'BZ' State
3. Address of Operator P.O. Box 728 Hobbs, NM 88240	9. Well No. 4
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 29 TOWNSHIP 21-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat San Simon Yates North
15. Elevation (Show whether DF, RT, GR, etc.) 3649' (GR)	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER Addl. Yates Perforations ☒	REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Install BOP.
2. Set RBP @ 3860'.
3. Perforate 2-7/8" OD csg w/1-JSPF @ 3818', 3827', 3832', 3834', 3838', 3843', 3846', & 3850'.
4. Acidize perforations 3818'- 3850' w/2500 gal 15% NE Acid.
5. Pull RBP and pump 1000 gal 15% NE Acid down csg.
6. Swab well. Test and place on production.

Engineer 10/8/77

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE Asst. Dist. Supt. DATE 10-7-76

APPROVED BY _____ TITLE _____ DATE OCT 8 1976

CONDITIONS OF APPROVAL, IF ANY: