

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

E-8504

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Charm State

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

John Yuronka

8. Well No.

2

3. Address of Operator

One Marienfeld Place, Ste 580 Midland, TX 79701

9. Pool name or Wildcat

Jalmar Yates 7 Rivers

4. Well Location

Unit Letter I + : 1980 Feet From The South Line and 660 Feet From The East Line

Section 36 Township 21-S Range 35-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3621' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set CIBP at 3400 feet.
- 2) RIH with W.S. - Circulate hole- Mix mud.
- 3) Spot 10 sacks C cement on top of CIBP.
- 4) Perforate casing @ 800 feet. - Squeeze 50 sacks of C cement into Perfs. RIH to tag. No tag.
- 5) Squeeze another 50 sacks of C cement into perfs. @ 800 feet.
- 6) Circulated cement on backside of casing. Left casing full of cement.
- 7) Cut off wellhead and weld on dry hole marker 4/9/92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

President

DATE 5/4/92

TYPE OR PRINT NAME

Fred Newman (Triple "N" Service, Inc.)

TELEPHONE NO. (915) 687-1994

(This space for State Use)

APPROVED BY

TITLE

OIL & GAS INSPECTOR

DATE

JUL 14 '92

CONDITIONS OF APPROVAL, IF ANY: