

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☐ OTHER-INJECTOR

Name of Operator
Chevron U.S.A. Inc.

Address of Operator
P.O. Box 670 Hobbs, NM 88240

Location of Well
UNIT LETTER S L 4520 FEET FROM THE South LINE AND 660 FEET FROM
THE West LINE, SECTION 3 TOWNSHIP 21S RANGE 36E N.M.P.M.

7. Unit Agreement Name
EUNICE MONUMENT SOUTH UNIT

8. Farm or Lease Name

9. Well No.
207

10. Field and Pool, or Wildcat
EUNICE MONUMENT G/SA

11. Elevation (Show whether DF, RT, GR, etc.)
3531 GL

12. County
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

ORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
FORABLY ABANDON ☐ CHANGE PLANS ☐
OR ALTER CASING ☐ OTHER ☒ CONVERT TO INJECTOR

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPMs. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Clean out to TD @ 3849'. Log well. Add additional Grayburg perforations as logs indicate. Acidize as necessary. Equip for injection. Test casing, packer, and tubing to 500 psi. for 30 minutes. Return to production as an injector.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Orig. Signed by Paul Martin TITLE Drilling Superintendent DATE 10-23-86

Witnessed by Geologist TITLE Geologist DATE 10-23-86

NOTATIONS OF APPROVAL, IF ANY: