and the second sec	OF NEW MEXICO	IL CONSERVATION DIVISIO	
DISTR SANTA FE FILE		P. O. BOX 2088 SANTA FE, NEW MEXICO 87501	Form C-103 Revised 10-1-78
U.S.O.S. LAND OFF OPERATO			Sa. Indicate Type of Lease State 5. State Oil & Gas Lease No.
(DO NOT	SUNDRY NOT USE THIS FORM FOR PROPOSALS USE "APP.ICATION FOR	TICES AND REPORTS ON WELLS	
1. OIL X T	A'd well OTHI		7. Unit Agreement Name
Sun Exp	loration & Producti	8. Form or Lease Name Akens, J.A. 9. Well No.	
P.O. Bo	11	, Texas 79702	2 10. Field and Pool, or Wildcat
UNIT LETTER		FEET FROM THE West 660	Eunice-Monument (G-SA)
		TOWNSHIP 21S RANCE 36E 15. Elevation (Show whether DF, RT, CR, etc.)	имем.
<u></u>		riate Box To Indicate Nature of Notice, R	Lea
-	NOTICE OF INTENT	ION TO:	UBSEQUENT REPORT OF:
PERFORM REMEDIA TEMPORARILY ABAI PULL OR ALTER CA	ND ON	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OP CHANGE PLANE CASING TEST AND CEMEN	
OTHER		OTHER	
		(Clearly state all pertinent details, and give pertinent d	
2/25/86	bled from 200# to up 9-5/8" csg to pump 10# brine do	g to battery on 3/4" chk 9-5/8" S brine down 7" csg 7" CP 200# 9-5/ 20# all gas 9-5/8" CP went from 8 flowline open 9-5/8" csg CP 560 to wwn 7" csg & out 9-5/8" csg establi 7" CP 200# open both csg strings	8" CP 800# open 7" csg press 00 to 560# dig out cellar hook 50# all gas 7" SICP 20# to 75# sh circ between string pump 150
2/26/86	CP 9 psi / chappa	/ slight gas blow out 7" csg & 9-5 ral kill truck pump 200 bbls 10 pp on vac / open both 7" & 9-5/8" to	a bring down 7" csa & out
2/27/86	MIRU Welltech WS csg w/150 bbls 10 to work pkr loose	slight blow on 7" & 9-5/8" csg no # brine well dead NP wellhead NU B	press on gauges circ 7" & 9-5/8" OP worked tbg to 50000# unable
			· · ·
18. I hereby certify	that the information above is	true and complete to the best of my knowledge and belie	·1.
AIGHED UT	Hom Kinp	Associate Account	ant 3/19/86
OPIG	INAL SIGNED BY JERRY S	_	