STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

40. 07 COPIES RECEIVES	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

DISTRIBUTION	P. O. BOX 2088	Farm 6 105	
SANTA FE		Form C-103 - Revised 10-1-78	
FILE	SANTA FE, NEW MEXICO 87501		
U.S.G.S.	1	5a. Indicate Type of Lease	
LAND OFFICE	1	State Fee XX	
OPERATOR	1 .	5. State Oil & Gas Lease No.	
	•	J. State Off & Gas Lease No.	
CLINIC	N NOTICES AND DOZDO		
SUNIDE THIS FORM FOR PR	RY NOTICES AND REPORTS ON WELLS		
USE "APPL CA"	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. FION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
011 🗀		7. Unit Agreement Name	
WELL X WELL	OTHER+	Eunice Monument South U	
2. Name of Operator		8. Form or Lease Name	
Chevron U.S.A. I	• •	or . am of Lease Mame	
3. Address of Operator	<u> </u>		
		9. Well No.	
P.O. Box 670. Hol	obs. NM 88240	236	
4. Location of Well		10. Field and Pool, or Wildcat	
UNIT LETTER S 10	380 FEET FROM THE South LINE AND 1980 FEET F	•	
	FEET PROM THE SOUCH LINE AND 1300 FEET P	TOM Eunice Monument G/SA	
-u- West			
LINE, SECTI	ON 3 TOWNSHIP 21S RANGE 36E	(
mmmmmmm			
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
AMILIA (MARIE)	3561 GL	Lea	
Check	Appropriate Box To Indicate Notice of No.		
NOTICE OF U	Appropriate Box To Indicate Nature of Notice, Report or		
	SUBSEQUE	ENT REPORT OF:	
PERFORM REMEDIAL WORK			
=	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	TOW AND ABANDONMENT	
	OTHER	,	
OTHER			
17. Describe Proposed or Completed Op	perations (Clearly state all pertinent details, and give pertinent dates, includ	ling estimated data of service	
BUTA, SEE NOCE 1103.	grant framework through	ing estimated date of starting any proposed	
3698-3700, 3703-0 1500psi, ok. pki w/4000 gallons 19	4. Perf w/4" guns. 2JHPF, total 36 holes f/367- 05, 3716-18, 3722-24, 3732-34, 3742-44. Set RB r set at 3623' test csg to 600psi, acidize new 5% NEFE HCL. TIH w/pump and rods. Return to p 4/05/87 to 04/09/87.	P at 3156, test to. perfs f/3675 to 3744.	
	•		
	•		
		•	
		m.P	
18. I hereby certify that the information is	above is true and complete to the best of my knowledge and belief.		
M. F st	•		
IICHEO	STAFF DRILLING ENGINE	ER May 15, 1987	
Orig Signed by			
1000 55			

MAY 1 9 1987